APPENDIX C

Crash Analysis

1. Greenville S-564 MP 4.224 to 7.594

Crash Summary

Page: 1

Greenville S-564 MP 4.224 to 7.594
GREENVILLE
S- 564 (MILLER RD)
MP 4.224 to 7.594 (Length = 3.37 miles)

AADT: 8840 Functional Class: Urban - Major Collector 01/01/2020 through 12/31/2022

Crashes by Injury Class

Fatal Crashes: 0
Serious Injury Crashes: 1
Other Injury Crashes: 17
PDO Crashes: 147

Total: 165

Crashes by Manner of Collision

Rear End: 69 Angle: 48 17 Sideswipe: Head On: 4 Run off Road: 17 Animal: 5 Bicycle: 0 Pedestrian: 0 Other: 5

Total: 165

Special Contributing Factors

Night: 48 Day: 117

Not Reported: 0

Wet: 27

Dry: 138

Not Reported: 0



Crash Summary

Greenville S-564 MP 4.224 to 7.594 GREENVILLE S- 564 (MILLER RD) MP 4.224 to 7.594 (Length = 3.37 miles)

AADT: 8840 Functional Class: Urban - Major Collector 01/01/2020 through 12/31/2022

Statistics Fatal Crashes: 0 Fatal Injuries: 0 Serious Crashes: 1 Serious Injuries: 1

Other Injury Crashes: 17
Other Injuries: 21
Property Damage Crashes: 147

Total Crashes: 165

Crash Location

Intersections: 127
Midblock Crashes: 38
Urban Crashes: 165
Rural Crashes: 0
MPO Crashes: 165
COG Crashes: 0

Manner of Collision

Angle: 48 Backed Into: 4 Head On: 4 Non Collision: 22 Rear End: 69 Rear To Rear: 0 Sideswipe, Opposite Direction: 1 Sideswipe, Same Direction: 16 1 Unknown:

Junction Type

Crossover: 0 32 Driveway: Five Or More Points: 0 17 Four Way Intersection: Non-Junction: 101 Railway Grade Crossing: 0 Shared Use Path Or Trails: 0 T-Intersection: 15 Traffic Circle: 0 Not Reported: 0 Unknown: 0 0 Y-Intersection:

Number of Units

1: 20 2: 138 3: 5 4+: 2

Crashes Involving Pedestrians: Bicycles: Motorcycles: 4 Truck Tractors: Fixed Objects: 16

Workzones:

3

Road Conditions

Dry: 138 Wet: 27 Snow: 0 Slush: 0 Ice: 0 Contaminate: 0 0 Water (standing): 0 Other: Not Reported: 0

Light Conditions

Day: 117 Dawn: 4 Dusk: 7 Dark (Unspecified Lighting): 8 Dark (Street Lamp): 6 Dark (Street Lamp Not Lit): 3 Dark (No Lights): 20 Not Reported: 0

Weather Conditions

Blowing Sand, Oil, Dirt, Or Snow: 0 Clear: 125 Cloudy: 17 Fog, Smoke, Smog: 2 20 Severe Crosswinds: 1 0 Sleet/Hail: Snow: 0 Not Reported: 0 Unknown: 0

Traffic Control Type

Crash Harmful Event

Tree: 2 **Utility Pole:** 2 2 Other (Post, Pole, Support, ..): Light/Luminance Support: 0 Overhead Sign Support: 0 Culvert: 1 1 Ditch: Equipment: 0 Curb: 0 1 Embankment: Guardrail End: 1 Fence: 0

Mail Box: 0
Highway Traffic Sign Post: 1
Guardrail Face: 1

Bridge Overhead Structure: 0
Bridge Parapet End: 0

Bridge Pier or Abutment: 0
Bridge Rail: 0

Impact Attenuator/Crash Cushion: 0
Median Barrier: 0

Other (Wall, Building, Tunnel, …): 1
Work Zone Maintenance Equip: 0

Other (fixed): 3 Unknown (fixed): 0 Animal (Deer Only): 5

Animal (Deer Only): 5
Animal (all other): 0
Motor Unit (Stopped): 67

Motor Unit (Other Roadway): 0 Motor Unit (Parked): 3

Railway Unit: 0

Work Zone Maintenance Equip: 0
Other Movable Object: 0
Unknown Movable Object: 0

Cross Median/Center: 2
Spill (2-wheeled Units): 0
Ran off Road Left: 1

Ran off Road Right: 0
Overturn/Rollover: 1
Immersion: 0

Cargo/Equipment Loss or Shift: 0
Downhill Runaway: 0

Equipment Failure: 1
Fire/Explosion: 0

Jackknife: 0
Separation of Units: 0
Other - non Collision: 0
Unknown - non Collision: 0

Motor Unit (In Transport): 69
Undetermined: 0




Crash Summary


Greenville S-564 MP 4.224 to 7.594 **GREENVILLE** S-564 (MILLER RD) MP 4.224 to 7.594 (Length = 3.37 miles)

AADT: 8840 Functional Class: Urban - Major Collector 01/01/2020 through 12/31/2022


Yearly Comparison

Year	2020	2021	2022	Total
Rear End	18	23	28	69
Angle	9	23	16	48
Sideswipe	5	7	5	17
Head On	0	3	1	4
Run Off Road	4	7	6	17
Animal	0	3	2	5
Bicycle	0	0	0	0
Pedestrian	0	0	0	0
Other	4	1	0	5
	40	67	58	165






Time of Day



Month of Year






Crash Stacks

Greenville S-564 MP 4.224 to 7.594 GREENVILLE S- 564 (MILLER RD) MP 4.224 to 7.594 (Length = 3.37 miles)

AADT: 8840 Functional Class: Urban - Major Collector 01/01/2020 through 12/31/2022

Interval Crashes by Interval



MPT 4.22 to 4.42 (Stack #1)

Total Crashes: 28 Light: 23 Dark: 5 Dry: 25 Wet: 3 Fatalities: 0 Injuries: 4 PDO: 24

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
1	22507805	02/11/22	S- 564	4.25	SC 146	I- 385	3	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
2	21222591	03/14/21	S- 564	4.25	SC 146	I- 385	4	0	day	dry	Angle	Unknown	Motor Unit (In Transpo
3	21566802	10/12/21	S- 564	4.25	SC 146	I- 385	6	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
4	21577461	11/18/21	S- 564	4.25	SC 146	I- 385	4	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
5	20572795	12/31/20	S- 564	4.25	SC 146	I- 385	3	0	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
6	22513267	03/02/22	S- 564	4.26	SC 146	I- 385	6	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
7	21512298	03/05/21	S- 564	4.26	SC 146	I- 385	5	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
8	22528571	05/05/22	S- 564	4.26	SC 146	I- 385	11	0	day	dry	SS	Improper Turn	Motor Unit (Stopped)
9	21545174	07/17/21	S- 564	4.26	SC 146	I- 385	10	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
10	21556296	08/24/21	S- 564	4.26	SC 146	I- 385	5	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
11	21575404	11/12/21	S- 564	4.26	SC 146	I- 385	11	1	day	dry	Angle	Failure to Yield RoW	Motor Unit (Stopped)
12	21581507	12/06/21	S- 564	4.26	SC 146	I- 385	6	0	day	dry	SS	Improper Turn	Motor Unit (Stopped)
13	22582814	12/06/22	S- 564	4.26	SC 146	I- 385	11	0	day	wet	Angle	Failure to Yield RoW	Motor Unit (In Transpo
14	20569554	12/15/20	S- 564	4.26	SC 146	I- 385	5	0	night	dry	Angle	Improper Turn	Motor Unit (Stopped)
15	21502256	01/15/21	S- 564	4.27	SC 146	I- 385	11	0	day	dry	НО	Failure to Yield RoW	Motor Unit (In Transpo
16	21506334	02/06/21	S- 564	4.27	SC 146	I- 385	3	0	day	dry	RE	Distracted/Inattention	Motor Unit (Stopped)
17	20516050	03/13/20	S- 564	4.27	SC 146	I- 385	8	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
18	22552394	08/04/22	S- 564	4.27	SC 146	I- 385	9	0	day	dry	НО	Failure to Yield RoW	Motor Unit (In Transpo
19	21572719	10/29/21	S- 564	4.27	SC 146	I- 385	16	1	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
20	22502107	01/05/22	S- 564	4.28	SC 146	I- 385	13	0	night	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
21	20564087	11/23/20	S- 564	4.3	SC 146	I- 385	40	0	day	dry	SS	Unknown	Motor Unit (In Transpo
22	21267673	08/14/21	S- 564	4.32	I- 385	SC 146	2	0	day	wet	SS	Improper Lane use/change	Motor Unit (In Transpo
23	20203185	01/15/20	S- 564	4.33	I- 385	SC 146	1	1	night	dry	SS	Driving too Fast for Con	Cross Median/Center
24	20269397	09/21/20	S- 564	4.34	I- 385	SC 146	7	0	day	dry	SS	Improper Lane use/change	Motor Unit (In Transpo
25	20206732	09/27/20	S- 564	4.38	I- 385	SC 146	0	0	night	wet	Angle	Other Improper Action	Motor Unit (Parked)
26	22221837	03/11/22	S- 564	4.4	I- 385	S- 1142	20	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
27	20347594	11/21/20	S- 564	4.4	I- 385	S- 1142	50	1	day	dry	ВІ	Unknown	Motor Unit (Stopped)
28	21219708	03/02/21	S- 564	4.41	I- 385	S- 1142	10	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo

MPT 4.62 to 4.82 (Stack #3)

Total Crashes: 20 Light: 12 Dark: 8 Dry: 15 Wet: 5 Fatalities: 0 Injuries: 3 PDO: 17

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
29	22211747	02/03/22	S- 564	4.64	S- 1142	S- 1112	10	1	day	wet	RE	Driving too Fast for Con	Motor Unit (Stopped)
30	21244288	05/27/21	S- 564	4.64	S- 1142	S- 1112	2	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
31	22244035	06/07/22	S- 564	4.64	S- 1142	S- 1112	6	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
32	22247349	06/09/22	S- 564	4.64	S- 1142	S- 1112	4	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
33	22306117	12/08/22	S- 564	4.64	S- 1142	S- 1112	9	0	night	wet	RE	Driving too Fast for Con	Motor Unit (Stopped)
34	21454690	11/22/21	S- 564	4.69	S- 1142	S- 1112	1	1	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
35	21540047	06/23/21	S- 564	4.71	S- 1112	S- 1142	57	2	night	dry	SS	Driving too Fast for Con	Motor Unit (Stopped)
36	21450059	11/09/21	S- 564	4.74	S- 1112	S- 1142	1	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
37	21450060	11/09/21	S- 564	4.74	S- 1112	S- 1142	1	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
38	20217352	01/19/20	S- 564	4.76	S- 1112	S- 548	1	0	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
39	20219007	01/27/20	S- 564	4.76	S- 1112	S- 548	0	0	day	wet	Angle	Failure to Yield RoW	Motor Unit (In Transpo

MPT 4.62 to 4.82 (cont)

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
40	21214129	02/11/21	S- 564	4.76	S- 1112	S- 548	2	0	day	wet	RE	Driving too Fast for Con	Motor Unit (Stopped)
41	22213842	02/19/22	S- 564	4.76	S- 1112	S- 548	3	0	night	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
42	22227118	03/30/22	S- 564	4.76	S- 1112	S- 548	1	0	night	dry	RE	Unknown	Motor Unit (Parked)
43	22268365	08/24/22	S- 564	4.76	S- 1112	S- 548	0	0	night	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
44	21291666	10/31/21	S- 564	4.76	S- 1112	S- 548	1	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
45	22312009	12/30/22	S- 564	4.76	S- 1112	S- 548	0	0	night	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
46	22311791	12/30/22	S- 564	4.76	S- 1112	S- 548	3	0	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
47	22255268	07/07/22	S- 564	4.78	S- 1112	S- 548	3	0	day	wet	RE	Driving too Fast for Con	Motor Unit (Stopped)
48	20351999	12/15/20	S- 564	4.79	S- 1112	S- 548	19	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)

MPT 4.82 to 5.02 (Stack #4)

Total Crashes: 4 Light: 3 Dark: 1 Dry: 3 Wet: 1 Fatalities: 0 Injuries: 1 PDO: 3

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
49	21286001	10/18/21	S- 564	4.84	S- 1112	S- 548	9	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
50	22221890	03/25/22	S- 564	4.88	S- 1112	S- 548	14	0	night	dry	none	Animal in Road	Animal (Deer Only)
51	22304867	12/07/22	S- 564	4.9	S- 1112	S- 548	15	2	day	wet	Angle	Failure to Yield RoW	Ran off Road Left
52	21208252	01/20/21	S- 564	4.94	S- 1112	S- 548	35	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo

MPT 5.02 to 5.22 (Stack #5)

Total Crashes: 4 Light: 3 Dark: 1 Dry: 4 Wet: 0 Fatalities: 0 Injuries: 0 PDO: 4

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
53	21230246	04/09/21	S- 564	5.02	S- 1112	S- 548	10	0	day	dry	none	Driving too Fast for Con	Utility Pole
54	22290384	11/13/22	S- 564	5.13	S- 548	S- 1112	37	0	night	dry	none	Animal in Road	Animal (Deer Only)
55	22251505	06/23/22	S- 564	5.18	S- 548	S- 1112	32	0	day	dry	SS	Improper Lane use/change	Motor Unit (In Transpo
56	22266868	08/20/22	S- 564	5.21	S- 548	S- 1112	1	0	day	dry	SS	Improper Lane use/change	Motor Unit (In Transpo

MPT 5.22 to 5.42 (Stack #6)

Total Crashes: 7 Light: 4 Dark: 3 Dry: 5 Wet: 2 Fatalities: 0 Injuries: 0 PDO: 7

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
57	20209349	09/22/20	S- 564	5.31	S- 548	S- 1112	17	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
58	22216925	02/25/22	S- 564	5.34	S- 548	S- 1112	13	0	night	dry	none	Under the Influence	Utility Pole
59	22303565	12/05/22	S- 564	5.36	S- 548	S- 1112	11	0	day	wet	RE	Driving too Fast for Con	Motor Unit (Stopped)
60	22203324	01/06/22	S- 564	5.39	S- 548	S- 1112	7	0	night	wet	RE	Other Improper Action	Motor Unit (Stopped)
61	21230160	04/16/21	S- 564	5.4	S- 548	S- 1112	8	0	day	dry	SS	Improper Turn	Motor Unit (In Transpo
62	22263909	08/09/22	S- 564	5.41	S- 548	S- 1112	6	0	day	dry	SS	Aggressive Operation	Motor Unit (In Transpo
63	21274626	09/26/21	S- 564	5.41	S- 548	S- 1112	5	0	night	dry	Angle	Improper Turn	Motor Unit (In Transpo

MPT 5.42 to 5.62 (Stack #7)

Total Crashes: 24 Light: 17 Dark: 7 Dry: 22 Wet: 2 Fatalities: 0 Injuries: 4 PDO: 20

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
64	21294024	11/07/21	S- 564	5.42	S- 548	S- 1112	5	1	night	dry	none	Driving too Fast for Con	Other (Wall, Building,
65	22216865	02/22/22	S- 564	5.44	S- 548	S- 1112	3	1	night	dry	RE	Other Improper Action	Motor Unit (Stopped)
66	21280942	10/01/21	S- 564	5.44	S- 548	S- 1112	3	0	day	dry	SS	Improper Lane use/change	Motor Unit (In Transpo
67	22298219	11/21/22	S- 564	5.45	S- 548	S- 1112	2	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)

MPT 5.42 to 5.62 (cont)

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
68	20354540	12/17/20	S- 564	5.45	S- 548	S- 1112	1	0	night	dry	ВІ	Unknown	Motor Unit (Stopped)
69	22200000	01/05/22	S- 564	5.46	S- 548	S- 580	7	0	night	dry	RE	Other Improper Action	Motor Unit (Stopped)
70	21207335	01/12/21	S- 564	5.46	S- 548	S- 580	0	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
71	20223235	02/24/20	S- 564	5.46	S- 548	S- 580	3	0	day	dry	Angle	Improper Lane use/change	Motor Unit (In Transpo
72	20221354	03/04/20	S- 564	5.46	S- 548	S- 580	1	1	day	dry	Angle	Other Improper Action	Motor Unit (In Transpo
73	21222983	03/18/21	S- 564	5.46	S- 548	S- 580	0	0	night	wet	RE	Other Improper Action	Motor Unit (Stopped)
74	21224725	03/24/21	S- 564	5.46	S- 548	S- 580	10	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
75	22240091	05/17/22	S- 564	5.46	S- 548	S- 1112	1	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
76	21242776	05/26/21	S- 564	5.46	S- 548	S- 580	20	0	day	dry	SS	Failure to Yield RoW	Motor Unit (In Transpo
77	21250413	06/16/21	S- 564	5.46	S- 548	S- 580	3	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
78	21255123	07/03/21	S- 564	5.46	S- 548	S- 580	0	0	day	dry	Angle	Unknown	Motor Unit (In Transpo
79	21260880	07/21/21	S- 564	5.46	S- 548	S- 1112	0	0	day	dry	SS	Driving too Fast for Con	Motor Unit (Stopped)
80	20264500	08/28/20	S- 564	5.46	S- 548	S- 580	1	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
81	21286206	10/18/21	S- 564	5.46	S- 548	S- 580	0	1	night	dry	none	Medical Related	Embankment
82	20265414	10/26/20	S- 564	5.46	S- 548	S- 580	3	0	day	dry	Angle	Other Improper Action	Motor Unit (In Transpo
83	22285916	11/14/22	S- 564	5.52	S- 548	S- 580	5	0	night	dry	RE	Following too Closely	Motor Unit (In Transpo
84	21276364	09/21/21	S- 564	5.53	S- 548	S- 580	14	0	day	wet	Angle	Other Improper Action	Motor Unit (In Transpo
85	21262329	08/24/21	S- 564	5.54	S- 548	S- 580	1	0	day	dry	Angle	Improper Lane use/change	Motor Unit (In Transpo
86	22250827	06/30/22	S- 564	5.56	S- 548	S- 580	8	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
87	20265538	08/28/20	S- 564	5.6	S- 580	S- 548	8	0	day	dry	UNK	Unknown	Motor Unit (Stopped)

MPT 5.62 to 5.82 (Stack #8)

Total Crashes: 6 Light: 3 Dark: 3 Dry: 4 Wet: 2 Fatalities: 0 Injuries: 1 PDO: 5

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
88	21220268	03/12/21	S- 564	5.64	S- 580	S- 548	5	0	day	dry	Angle	Improper Lane use/change	Motor Unit (In Transpo
89	22296014	11/10/22	S- 564	5.66	S- 580	S- 548	1	0	night	wet	RE	Other Improper Action	Motor Unit (Stopped)
90	21215639	02/15/21	S- 564	5.68	S- 580	S- 548	0	0	day	wet	RE	Driving too Fast for Con	Motor Unit (In Transpo
91	22305577	11/30/22	S- 564	5.68	S- 580	S- 548	2	0	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
92	22221836	03/11/22	S- 564	5.7	S- 580	S- 548	0	1	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
93	22238144	05/07/22	S- 564	5.7	S- 580	S- 548	0	0	night	dry	Angle	Driving too Fast for Con	Overturn/Rollover

MPT 5.82 to 6.02 (Stack #9)

Total Crashes: 1 Light: 1 Dark: 0 Dry: 1 Wet: 0 Fatalities: 0 Injuries: 0 PDO: 1

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
94	21284694	10/14/21	S- 564	5.96	L- 8790	L- 5710	20	0	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo

MPT 6.02 to 6.22 (Stack #10)

Total Crashes: 2 Light: 0 Dark: 2 Dry: 2 Wet: 0 Fatalities: 0 Injuries: 0 PDO: 2

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
95	20270703	09/19/20	S- 564	6.06	L- 8790	L- 5710	20	0	night	dry	none	Unknown	Culvert
96	20355179	12/29/20	S- 564	6.08	L- 2113	L- 8790	26	0	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)

MPT 6.22 to 6.42 (Stack #11)

Total Crashes: 11 Light: 7 Dark: 4 Dry: 9 Wet: 2 Fatalities: 0 Injuries: 3 PDO: 8

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
97	22302577	12/23/22	S- 564	6.26	L- 2113	L- 8790	4	0	night	dry	none	Obstruction in Roadway	Tree

MPT 6.22 to 6.42 (cont)

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
98	20217355	01/22/20	S- 564	6.29	L- 2113	L- 1582	0	1	night	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
99	21209286	01/25/21	S- 564	6.29	L- 2113	L- 1582	0	0	day	wet	RE	Unknown	Motor Unit (In Transpo
100	20203064	02/03/20	S- 564	6.29	L- 2113	L- 1582	2	0	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
101	22236829	05/02/22	S- 564	6.29	L- 2113	L- 1582	0	2	day	dry	Angle	Disregarded Signs/Signals	Motor Unit (In Transpo
102	21276117	09/15/21	S- 564	6.29	L- 2113	L- 1582	0	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
103	22216058	02/18/22	S- 564	6.3	L- 2113	L- 1582	0	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
104	21241047	05/19/21	S- 564	6.3	L- 2113	L- 1582	0	1	day	dry	Angle	Driving too Fast for Con	Motor Unit (In Transpo
105	22278684	10/07/22	S- 564	6.3	L- 2113	L- 1582	0	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
106	21450822	11/16/21	S- 564	6.32	L- 2113	L- 1582	2	0	night	dry	none	Animal in Road	Animal (Deer Only)
107	20352793	12/31/20	S- 564	6.36	L- 2113	L- 1582	37	0	night	wet	none	Animal in Road	Equipment Failure

MPT 6.62 to 6.82 (Stack #13)

Total Crashes: 4 Light: 3 Dark: 1 Dry: 3 Wet: 1 Fatalities: 0 Injuries: 1 PDO: 3

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
108	21212279	02/07/21	S- 564	6.66	L- 2397	L- 514	0	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
109	22239525	05/11/22	S- 564	6.66	L- 2397	L- 5710	30	0	day	dry	none	Other (roadway)	Other (fixed)
110	20256585	07/30/20	S- 564	6.68	L- 2397	L- 514	3	0	day	dry	none	Driving too Fast for Con	Other (Post, Pole, Sup
111	21283087	10/08/21	S- 564	6.69	L- 2397	L- 514	5	3	night	wet	НО	Wrong side or Wrong Way	Cross Median/Center

MPT 6.82 to 7.02 (Stack #14)

Total Crashes: 6 Light: 4 Dark: 2 Dry: 5 Wet: 1 Fatalities: 0 Injuries: 0 PDO: 6

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
112	22246969	06/07/22	S- 564	6.85	L- 514	L- 1582	1	0	day	dry	none	Unknown	Other (fixed)
113	21222287	03/16/21	S- 564	6.86	L- 514	L- 1390	10	0	night	wet	none	Under the Influence	Tree
114	21276518	09/18/21	S- 564	6.86	L- 514	L- 1390	3	0	night	dry	none	Driving too Fast for Con	Ditch
115	22256598	07/13/22	S- 564	6.9	L- 514	L- 1390	1	0	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
116	22224965	03/23/22	S- 564	6.98	L- 1390	L- 514	1	0	day	dry	none	Driving too Fast for Con	Highway Traffic Sign P
117	21294844	11/09/21	S- 564	7.01	L- 1390	S- 1078	50	0	day	dry	none	Driving too Fast for Con	Other (fixed)

MPT 7.02 to 7.22 (Stack #15)

Total Crashes: 5 Light: 4 Dark: 1 Dry: 4 Wet: 1 Fatalities: 0 Injuries: 1 PDO: 4

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
118	21259056	07/17/21	S- 564	7.09	L- 1390	S- 1078	20	0	day	dry	none	Driving too Fast for Con	Other (Post, Pole, Sup
119	21235281	05/06/21	S- 564	7.1	L- 1390	S- 1078	0	0	day	dry	НО	Failure to Yield RoW	Motor Unit (In Transpo
120	22244590	05/28/22	S- 564	7.1	L- 1390	S- 1078	2	0	night	dry	none	Animal in Road	Guardrail End
121	22242950	05/23/22	S- 564	7.2	S- 1078	L- 1390	13	1	day	wet	RE	Driving too Fast for Con	Motor Unit (In Transpo
122	21455684	11/25/21	S- 564	7.2	S- 1078	L- 1390	23	0	day	dry	none	Animal in Road	Animal (Deer Only)

MPT 7.22 to 7.42 (Stack #16)

Total Crashes: 6 Light: 4 Dark: 2 Dry: 5 Wet: 1 Fatalities: 0 Injuries: 0 PDO: 6

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
123	21234240	04/24/21	S- 564	7.25	S- 1078	L- 1390	30	0	night	dry	none	Animal in Road	Animal (Deer Only)
124	21234241	04/24/21	S- 564	7.25	S- 1078	L- 1390	30	0	night	dry	RE	Distracted/Inattention	Motor Unit (Parked)
125	21234008	04/27/21	S- 564	7.28	S- 1078	L- 1390	10	0	day	dry	ВІ	Other Improper Action	Motor Unit (Stopped)

MPT 7.22 to 7.42 (cont)

овѕ	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
126	20337792	10/28/20	S- 564	7.33	S- 1078	L- 1390	28	0	day	wet	none	Driving too Fast for Con	Guardrail Face
127	20246402	06/20/20	S- 564	7.37	S- 1078	L- 1390	0	0	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
128	20338736	10/29/20	S- 564	7.37	S- 1078	L- 1390	50	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)

MPT 7.42 to 7.62 (Stack #17)

Total Crashes: 14 Light: 12 Dark: 2 Dry: 14 Wet: 0 Fatalities: 0 Injuries: 0 PDO: 14

OBS	Crash #	Date	Main	MP	Base	Second	BDO	Max Inj	Light	SFC	MAC	Probable Cause	Harmful Event
129	20202475	01/06/20	S- 564	7.47	S- 999	S- 1078	10	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
130	22208600	01/24/22	S- 564	7.52	S- 999	S- 492	1	0	night	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
131	22298025	12/03/22	S- 564	7.53	S- 999	S- 492	6	0	day	dry	Angle	Failure to Yield RoW	Motor Unit (In Transpo
132	20352000	12/15/20	S- 564	7.53	S- 999	S- 492	100	0	day	dry	RE	Driving too Fast for Con	Motor Unit (In Transpo
133	20227431	03/10/20	S- 564	7.56	S- 492	S- 999	5	0	day	dry	RE	Failure to Yield RoW	Motor Unit (Stopped)
134	21457458	12/07/21	S- 564	7.57	S- 492	S- 999	5	0	day	dry	Angle	Other Improper Action	Motor Unit (Stopped)
135	21463397	12/28/21	S- 564	7.57	S- 492	S- 999	3	0	day	dry	RE	Unknown	Motor Unit (Stopped)
136	22244490	05/29/22	S- 564	7.58	S- 492	S- 999	2	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
137	21282091	10/02/21	S- 564	7.58	S- 492	S- 999	2	0	day	dry	RE	Driving too Fast for Con	Motor Unit (Stopped)
138	22222359	03/14/22	S- 564	7.59	S- 492	S- 999	0	0	night	dry	RE	Other Improper Action	Motor Unit (Stopped)
139	21234047	05/05/21	S- 564	7.59	S- 492	Unknown	0	0	day	dry	Angle	Disregarded Signs/Signals	Motor Unit (In Transpo
140	21257407	07/14/21	S- 564	7.59	S- 492	S- 999	0	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
141	21264655	08/25/21	S- 564	7.59	S- 492	S- 999	0	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)
142	22277592	09/21/22	S- 564	7.59	S- 492	S- 999	5	0	day	dry	RE	Other Improper Action	Motor Unit (Stopped)

g Second Intersection (Rt. # / Name)

146 / WOODRUFF RD

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

Λ

17

43.87

Longitude

1 - Interstate 4 - Secondary


N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp

Τo


N F 1 - Entrance

S W 2-Exit

R. R. Id



HP03



/ CARRIE DR

2 - Alternate 7 - Business

5 - Spur 9 - Other

Λ

16

14.61

Longitude


2 - US Primary 6 County


S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F





385 / 385

g Second Intersection (Rt. # / Name)

1 Interstate 4 - Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

To


NF

Ramp Only

N F 1 - Entrance

S W 2 - Exit

R. R. Id



Unit # 2 was traveling north on SEC 546. Unit # 1 was traveling south on SEC 546. Unit # 1 was traveling too fast for conditions. Unit # 1 crossed left of center and struck unit # 2 on the left, front side.

3/4/2020: Corrected FR-10 Number sequence and adjusted narrative and diagram to reflect unit number change.

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other


0

17

38.23

Longitude


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



20206732 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 2226 2226 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 09-27-2020 23 564 / ROPER MOUNTAIN RD GREENVILLE 0.2 (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp 1 Interstate 4 - Secondary 2 - US Primary 5 - County Direction Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) (N) E 2 - Alternate 7 - Business Of 2 (N) E EGREES MINUTES SECONDS 10 385 SW SW 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 49 38.63 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N F 1 - Entrance 146 / WOODRUFF RD Longitude 17 35.84



5 - Spur 9 - Other



S W 2 - Exit

UNIT 1 AND UNIT 2 WERE ON A CLOSED ROADWAY FOR CONSTRUCTION. UNIT 2 WAS PARKED. UNIT 1 IMPROPERLY BACKING, BACKED INTO UNIT 2 WITH AN OPEN COMPARTMENT DOOR CAUSING MINOR DAMAGE.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


Investigating Officer's Name G.J. ELGIN

Rank CPL SCCJA# 8504-8205 HP03

Jurisdiction Code Review Date HP03 09-28-2020

Reviewer's Name THOMPSON, MW

Internal Agency Code GVTC20CAD100127 Rank CPL



20209349 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1649 1714 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 09-22-2020 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 NF Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.17 s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other 0 Latitude 34 50 7.71 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id Ramp Only To g Second Intersection (Rt. # / Name)

1152 / CHROME DR


2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

NF



UNITS 1 AND 2 WERE TRAVELING WEST ON S-564. UNIT 1 STOPPED FOR TRAFFIC. THE DRIVER OF UNIT 2, DRIVING TOO FAST FOR CONDITIONS, STRUCK UNIT 1.

2 - Alternate 7 - Business

5 - Spur 9 - Other


0


16

57.59

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.






S W 2 - Exit


Unit #1 was traveling east on sec 564 stopped in traffic. Unit #2 was traveling east on sec 564 slowing for traffic. Unit #3 was traveling east on sec 564. Driver of unit #3, driving too fast for conditions, struck the center rear of unit #2 with the center front. After impact, unit #2 struck the center rear of unit #1 with the center front.

10-12-2020: ADDED FIRST DEFORMED AREA TO UNIT #3.

5 - Spur 9 - Other

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.






S W 2 - Exit

UNIT #1 WAS TRAVELING WEST ON SEC 564 STOPPED TO TURN SOUTH ONTO SNIPES RD. UNIT #2 WAS TRAVELING WEST ON SEC 564. DRIVER OF UNIT #2, DRIVING TOO FAST FOR CONDITIONS, STRUCK THE CENTER REAR OF UNIT #1 WITH THE CENTER FRONT.

5 - Spur 9 - Other


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



20219007 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0812 0847 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 01-27-2020 0803 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 EGREES MINUTES SECONDS 1142 , GARLINGTON RD 10 s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other П Latitude 34 49 56.58 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N F 1 - Entrance 146 / WOODRUFF RD Longitude 17 31.34



5 - Spur 9 - Other




S W 2-Exit

Unit 1 was traveling eastbound on Secondary 564. Unit 2 was turning left from Secondary 1142 onto Secondary 564. Unit 2, failing to yield right of way, struck unit 1 in the left


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


Internal Agency Code GVTC20CAD010751 Investigating Officer's Name C R COLBERG Rank TPR SCCJA# 7504-5246 Jurisdiction Code Review Date HP03 01-28-2020 Reviewer's Name C.J. LADUE Rank CPL HP03



20221354 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1259 1356 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NF 2 - US Primary 5 - County 03-04-2020 23 GREER 564 / \$564 s W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 NF Miles EGREES MINUTES SECONDS 0.01 548 , \$548 0 s (W) s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 10.54 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 580 / \$580 Longitude 16 49.13 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other









20223235 ORIGINAL - CORRECTED SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM pv of Original 0811 0824 X TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Date Time of 1 - Interstate Secondary Collision Location (Rt. # / Name) Miles Dir 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 02-24-2020 23 GREENVILLE 564 / GARLINGTON RD s w 6 - PP 7 - Ramp 5- Spur 3 - SC Primary Main line 6 - Connectio Direction 1 - Interstate 4 Secondary GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.03 548, ROPER MTN RD 0 s w s (W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 11.29 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id Τo Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 2 - US Primary 5 - County F 1 - Entrance N F 580 / DUBLIN RD Longitude 16 48.31 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other

S W 2-Exit







999 / HONBARRIER RD

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF

2 - Alternate 7 - Business


5 - Spur 9 - Other


0

15

23.48

Longitude





20246402 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1853 1912 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 06-20-2020 1853 23 564 / GARLINGTON RD GREER SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 DEGREES MINUTES SECONDS 30 1078 , \$1078 s (M) 5 - Spur 3 - SC Primary 6 - Other 7 - Ramp SW 9 - Other Latitude 34 51 18.22 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To 2 - US Primary (5) County 2 - Alternate 7 - Business 0 N E N F 1 - Entrance

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2-Exit

/ WYNDHAM CT




15


32.45

Longitude

5 - Spur 9 - Other




HP03



/ DUBLIN RD

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



UNIT 1 WAS TRAVELING WEST ON SEC-564. UNIT 1, TRAVELING TOO FAST FOR CONDITIONS, RAN OFF THE ROAD TO THE RIGHT, STRUCK A DITCH, AND AN EMBANKMENT WITH LANDSCAPING.


Longitude

5 - Spur 9 - Other

15


58.52


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



20264500 ORIGINAL - CORRECTED SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1823 1859 X TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 08-28-2020 23 GREENVILLE 564 / ROPER MTN RD s w 6-PP 7-Ramp 5- Spur 3 - SC Primary Main line 6 - Connectio Direction 1 - Interstate 4 Secondary GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 5 Mile EGREES MINUTES SECONDS 50 564, GARLINGTON RD s w 3 - SC Primary 6 - Other 7 - Ramp s w 5 - Spur 9 - Other **Feet** Latitude 34 50 10.19 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 2 - US Primary (5) County N F 1 - Entrance N F / TAMMY RAY DR Longitude 16 48.95 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2-Exit









20265414 ORIGINAL - AMENDED SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1715 1820 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Dir Date Time of County 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 10-26-2020 1715 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles NF EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.03 0 s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 11.29 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 580 / DUBLIN RD Longitude 16 48.43 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other









20265538 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1644 1718 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 08-28-2020 23 GREENVILLE 564 / GARLINGTON ROAD SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.08 580, DUBLIN ROAD s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 14.12 1 - Interstate 4 Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 548 / ROPER MTN RD Longitude 16 45.70 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other








S W (3) SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



UNIT 1 WAS EASTBOUND ON SECONDARY 564 AND WAS TRAVELING IN THE NUMBER 1 LANE. UNIT 2 WAS EASTBOUND ON SECONDARY 564 IN THE NUMBER 2 LANE AND WAS ATTEMPTING TO MERGE INTO THE NUMBER 1 LANE. THE DRIVER UNIT 2 MADE AN IMPROPER LANE CHANGE AND SIDESWIPED UNIT 1.


Longitude

5 - Spur 9 - Other


17

37.66

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.




20270703 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 2000 2030 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 09-19-2020 23 564 / GARLINGTON RD GREENVILLE 7.5 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Main line 6 - Connection Direction 1 - Interstate GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of NL Miles EGREES MINUTES SECONDS 0.2 CARRIE DR NL s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 28.32 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 2 - US Primary 5 County N F 1 - Entrance NF / SHAMROCK LN Longitude 16 25.28 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit



UNIT #1 WAS TRAVELING EAST ON SEC.-564. UNIT #2 WAS TRAVELING WEST ON SEC.-564 AND TRAVELED LEFT OF CENTER. UNIT #1 SWERVED RIGHT TO AVOID A HEAD ON COLLISION AND RAN OFF OF THE ROADWAY TO THE RIGHT. UNIT #1 STRUCK A CULVERT END WITH THE FRONT END AND UNDER CARRIAGE OF UNIT #1. UNIT #1 AND UNIT #2 DID NOT MAKE CONTACT. UNIT #2 LEFT THE SCENE AND HAS NOT BEEN IDENTIFIED.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



492 / PELHAM ROAD


2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF



UNIT #1 WAS WESTBOUND ON SECONDARY 564. DRIVER, DRIVING TOO FAST FOR CONDITIONS, LEFT THE ROAD TO THE RIGHT, STRIKING THE GUARDRAIL WITH THE RIGHT FRONT AND RIGHT SIDE.

2 - Alternate 7 - Business

5 - Spur 9 - Other


0

15

34.09

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



20338736 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1558 1627 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NF 2 - US Primary 5 - County 10-29-2020 23 564 / GARLINGTON GREENVILLE s W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 (N) E Miles EGREES MINUTES SECONDS 0.5 999, \$999 s w (S) W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 51 18.03 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To

/ WYNDHAM CT

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

15

32.41

Longitude


2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp


N F 1 - Entrance

S W 2 - Exit

NF




HP03



20347594 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1439 1749 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business (N) E 11-21-2020 23 564 / GARLINGTON RD GREENVILLE S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp 1 Interstate 4 - Secondary 2 - US Primary 5 - County Direction Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - Alternate 7 - Business Of 2 Miles NF EGREES MINUTES SECONDS 0.5 385 s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 49 40.45 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 1142 / CHROME DR Longitude 17 35.12

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit



UNIT #1 AND UNIT #2 WERE TRAVELING WEST SEC 564 STOPPED IN TRAFFIC. DRIVER OF UNIT #2 STRUCK UNIT #1 IN CENTER FRONT WITH AN UNKNOWN SIDE. UNIT #2 LEFT THE SCENE.

5 - Spur 9 - Other

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



548 / ROPER MTN ROAD

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF

2 - Alternate 7 - Business


5 - Spur 9 - Other


0


17


26.16


Longitude












20352793 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0704 0714 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business (N) E 12-31-2020 0704 23 564 / GARLINGTON ROAD GREENVILLE S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.37 HOKE SMITH BLVD s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 38.11 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 2 - US Primary 5 County N F 1 - Entrance NF / SNIPES RD Longitude 82 16 11.09 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other





UNIT 1 WAS TRAVELING EAST ON SEC-564. A DEER CROSSED THE LANES OF TRAFFIC CAUSING UNIT 1 TO SWERVE AND AVOID IT. UNIT 1 MISSED THE DEER. UNIT 1'S DRIVER FRONT TIRE BROKE OFF AND THE ENGINE FELL FROM UNDER THE HOOD.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


Investigating Officer's Name J.W. GRIFFETH

Rank TPR SCCJA# 8541-2678 HP03

Jurisdiction Code Review Date HP03 12-31-2020

Reviewer's Name B. C. PITTS

Internal Agency Code GVTC20CAD137136 Rank CPL



1142 / CHROME DR

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F


2 - Alternate 7 - Business


5 - Spur 9 - Other

Longitude


16


49.88







20355179 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1924 1949 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business NF 12-29-2020 23 564 / GARLINGTON RD GREENVILLE s W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 Miles NF EGREES MINUTES SECONDS 0.26 **SNIPES RD** s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 28.23 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / CARRIE DR Longitude 82 16 23.77 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other






	OKIG	IIIAL										
SOUTH	CAROLINA DPS/OHS &	DMV USE ONLY	Page # 1 Of: 1	SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)			Unitsof Original		- Attach Copy Report Notified		Arrived	
Date 201-07-2020	Collision 2	- Interstate (- US Primary - SC Primary	5- County 6- PP 7- Ramp 5 564	ion Location (Rt. # / Name) / GARLINGTON RD	0-Main Line 6-Cor 2-Alternate 7-Bus 5-Spur	nnection Mi iness	les: Dir. N E S W	GREEN	Near City or	Town of:		
Laile # / Dil	NE (1- Interstate 4- Secondary 2- US Primary 5- County	Base Intersection (ite a / realize/	San San San S	6-Connection 7-Business	GPS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS				
1 2 S	From Ramp	Only To	3 SC Primary 6- Other 7- F 1 Interstate 4- Secondary	Marrip IL		Spur Main Line	9-Other 6-Connection	Latitude	34	49	31.04	
		N E 1-Entrance N E	2- US Primary 5- County	wan	2	2-Alternate	7-Business	Lonaitud		T.	11	






ORIGINAL-AMENDED SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA #Of mended - Attach Copy Notified Arrived Page # of Original Report Units TRAFFIC COLLISION REPORT FORM 1240 1230 (Rev. 04/2016) 02 TR-310





PO3

20-006227




2 3 0 2 02-10-2020


SA McLean


DEMPSEY - B. M.


POI

2932-4274












		U	KIGINA	1L										
	SOUTH CAROLINA DPS/OHS & DMV USE ONLY					Page # 1 Of: 1	South Carolina Traffic Collision Report Form Tr-310 (Rev. 04/2016		# Of Units 16) 02	Units of Original R		Notified 1 4 3 9	Arrived	
10172	Date 02-13-2020	Collision	2- US F 23 3- SC P	rimary	Secondary 5- County 6- PP 7- Rai	A PARTY OF	ocation (Rt. # / Name) GARLINGTON RD	The second second second second	Connection Mi Business	les: Dir. N E S W	GREEN	Near City or	Town of:	
20205			1- Interstate 2- US Primar	5- County	i-County E			0-Main Line 6-Connection 2-Alternate 7-Business		GPS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS				
7	1 3 S R.R. Id.	From	Ramp Only 1- Entrance	To	1-Interstate 2- US Priman		Second Intersection (I	Rt. # / Name)	0-Main Line	9-Other 6-Connection 7-Business	Latitude	34	49	31.02
- 1		IN E	1- chilance	IN E	z- US Filliar	3-County	3		2-Miterifate	/-business	Longitus	ا ما ا	7	




NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS TO THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name Rank SCCJA # Jurisdiction Code Review Date Reviewer's Name Rank Internal Agency Code Skyler Queen Sd 20-011017









SA McLean


PO3


20-016256





OKIGINAL			
SOUTH CAROLINA DPS/OHS & DMV USE ONLY	Page # SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)	# Of Units Amended - Attach Cop of Original Report Corrected Corrected	Notified Arrived 1755 1805
Ose			(In) Near City or Town of: ENVILLE
Lane # / Dir. Distance Offset Direction 1- Inters: # Of N(E) Miles N (E) 2- US Pri	mary 5-County E	ain Line 6-Connection G Iternate 7-Business	PS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS
From Ramp Only To Pinters 1 1 1 1 1 1 1 1 1	mary 6-Other 7-Ramp 2 146 / WOODRUFF RD 5-Sp ate 4-Secondary 2 Second Intersection (Rt. # / Name)	our 9-Other Latite	ude 34 49 33.39
N E 1- Entrance N E 2- US Pri	mary 5-County 2-Al	Iternate 7-Business Longi	tude 0 1 11





















Skyler Queen

20-053832











		UKIG	INAL										
	19.555,441.652	AROLINA DPS/OHS &	DMV USE ONLY	P 1	age#	SOUTH CAROLI TRAFFIC COLLISION REP TR-310		# Of Units 6) 02	Amended - A of Original R Corrected		Notified 0 9 1 0	Arrived 0 9 1	5
64087	C	Collision	- Interstate 2- US Primary 3- SC Primary	5-County		ocation (Rt. # / Name) GARLINGTON RD	nnection Mil siness	es: Dir. N E S W	GREEN	In) Near City or Town of: NVILLE			
205	Lane # / Dir. # Of N	Distance Offs	Miles N (E)	1- Interstate 2- US Primary		Base Intersection (Rt. #	2	2-Alternate	5-Connection 7-Business	GPS C	OORDINATES 00 DEGREES MIN		DS ·
202	2 3 S V R.R. Id.	From Ramp	Only To	1-Interstate	6- Other 7- Ramp 4- Secondary	≥ 146 / WOODRUF → Second Intersection (F	Rt. # / Name)	Main Line	9-Other 6-Connection	Latitude	34	49	34.79
I.		N E 1- Entr	ance NE	2- US Primary	5- County	8	Į²	2-Alternate	7-Business	Lonaitude		1.0	- 11






ORIGINAL SOUTH CAROLINA DPS/OHS & DMV USE ONLY Amended - Attach Copy SOUTH CAROLINA #Of Notified Arrived age# of Original Report Units TRAFFIC COLLISION REPORT FORM 0910 0915 (Rev. 04/2016) 02 TR-310 0-Main Line (In) Near City or Town of: 2020564087 1- Interstate Secondary Collision Location (Rt. # / Name) 6-Connection Dir. Collision ΝE 2- US Primary 5- County 2-Alternate 7-Business **GREENVILLE** 0908 23 S 564 / GARLINGTON RD 11-23-2020 3- SC Primary 6- PP 7- Ramp S W GPS COORDINATES 00 00' 00.00" Distance Offset Lane # / Dir. 1- Interstate 4- Secondary Base Intersection (Rt. # / Name) 0-Main Line 6-Connection Miles N 📵 2- US Primary 5- County 2-Alternate 7-Business **DEGREES MINUTES SECONDS** 면 **146** .40 Feet s w / WOODRUFF RD 3 s w 3 SC Primary 6- Other 7- Ramp 5-Spur 9-Other Latitude From Ramp Only To 1-Interstate 4- Secondary 2- US Primary 5- County R.R. Id. 0-Main Line 6-Connection Second Intersection (Rt. # / Name) 49

2-Alternate

7-Business

Dir. of Travel:	Unit 1: N S E W	Unit 2: N	N S E W	Unit 3: N S E		INO CCTV OR WITNESSES AV	AU ARI F	AT TIME OF REPORT TO
						NO CCTV OR WITNESSES AVA CORROBORATE EITHER ACC		AT TIME OF REPORT TO
NOTICE - THE TR	-310 IS FOR STATISTICAL R	FPORTIN (G PLIRPOSES ON	I Y AND IS A RE	FI FCTION O	THE OFFICER'S BEST KNOWLEDGE, OPINI	ION AND RE	LIFE COVERING THE COLLISION RUT
	MADE AS TO THE FACTUA	L ACCUR	ACY THEREOF.	Jurisdiction Code				Internal Agency Code





ORIGINAL SOUTH CAROLINA DPS AND DMV USE ONLY South Carolina
Uniform Traffic Collision Report
(For Investigating Officers)
Supplemental Bus & Truck Collision Report nended-Attach Copy of Original Page 2020564087 (Revised 04/2009) Route Category Auxiliary Date Time County **Accident Location** econdary 5-County 6-PP 0-Mainline 6-Connection 2-Alternate 7-Business 5-Spur 9-Other 1-Interstate 2-US Primary 3-SC Primary (Route Number and Name if Any) ON 564 11-23-2020 0908 / GARLINGTON RD 23 Access Control **IF THIS CRASH INCLUDES:**


2- Full Acces Control


Complete This Form Only II:			
One or More Qualifying Vehicle(s) was Involved			
One or More Qualifying Injuries/Fatalities was Susta			
One or More Disabled Vehicle(s) was Towed Away Fr	rom the Scene		
Total Number of Supplemental Forms Required for this Collision	:	Ī	
Unit Number 02 FR-10 Number EE-434536	_	-	
Carrier Information		-	
Name: US FOODS		_	
Address: 12301 CUMBERLAND RD		_	
City: FISHER State: I N Zi	ip: 4 6	0 3 8	If "Yes", What Class of Hazardous Material (off placard/shipping papers)? 01- Class 1 (Explosives) 06- Class 6 (Poison/Infectious Substance) 02- Class 2 (Gases) 07- Class 7 (Radioactive) 03- Class 3 (Flammable Liquids) 08- Class 8 (Corrosives) 04- Class 4 (Flammable Solids) 09- Class 9 (Misc. Goods)
Identification Numbers			05- Class 5 (Oxidizing Substance) 10- No Placard
U.S. DOT 0 3 5 8 5 9 7 None = 0			99- Other/Unknown/Hit and Run If "YES", enter 4 digit HAZMAT ID (Look on placard/shipping papers)
(4) Not in Co	ommerce - Other To ommerce - Govern eration/Not Specif	nent	Did Hazardous Material Release from this Vehicle?
Carrier Type Is this vehicle a(n) (1) Interstate, (2) Intrastate Carrier?			1-Yes 2- No 3- Unknown/Hit and Run 2
Was a Citation Issued to this Vehicle? 1- Yes	2- No 3-	Pending 2	Name of Agency Notified (In Case of Release)
Investigator's Name Rank	Date		Reviewer's Name Rank
BROWN - P J	PO3	11-24-2020	Skyler Queen


		ORIGINAL										
		ROLINA DPS/OHS & DMV USE ONLY	Page # 1 Of: 1	# SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)			Amended - Attach Co of Original Report Corrected	Notified	Arrived 2 0	E STATE		
64108	C	ime of County 1 - Interstate (Collision 2- US Primary 1 8 2 5 23 3- SC Primary	5- County	Collision Location (Rt. # / Name) (0-)Main Line 6-Conr 2-Alternate 7-Busin 5-Spur			ΝE	(In) Near City or Town of: GREENVILLE				
205	Lane # / Dir. # Of N E		2- US Primary 5- County	Base Intersection (Rt. #	2-7	Control of the same	Connection (Business	GPS COORDINATES DEGREES M		ONDS		
202	2 4 S (W R.R. ld.	From Ramp Only To	3-SC Primary 6-Other 7-Ramp 1-Interstate 4-Secondary	2 Second Intersection (R	3.	******	Other Lati	tude 34	49	31.08		
		N E 1-Entrance N E	2- US Primary 5- County	war	2-7	Alternate 7	-Business Lond	oitude	1)	11		















		Ur	KIGINA	4L										
	SOUTH CAROLINA DPS/OHS & DMV USE ONLY					Page # 1 Of: 1	SOUTH CAROI TRAFFIC COLLISION RE TR-310		# Of Units 6) 02	Amended - A of Original R Corrected		Notified 1932	Arrive	ed 0 4 2
_		Collision 2- US Primary 5- County		Secondary 5- County 6- PP 7- Rai	y C 554 / CABLINGTON PD		The second secon	onnection Mi usiness	les: Dir. N E S W	GREEN	In) Near City or Town of: ENVILLE			
20205	Lane # / Dir. Distance Offset Direction 1- Interstat			2- US Primar	4- Secondary 5- County	Base Intersection (Rt.	O-Main Line 6-Connection 2-Alternate 7-Business		GPS C	GPS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS				
7	3 6 S R.R. Id.	W .03 From	Feet Ramp Only	_	3-SC Primary 1-Interstate	4- Secondary	p Second Intersection		02030000	9-Other 6-Connection	Latitude	34	49	32.45
	l		- Entrance	ΝE	2- US Primar	5-County	war	**	2-Alternate	7-Business	Longitud	0		- 11





21207335 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1444 1502 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NF 2 - US Primary 5 - County 01-12-2021 1435 23 GREENVILLE 564 / GARLINGTON RD 0.75 s W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 NF Mile EGREES MINUTES SECONDS 40 548 , ROPER MTN RD s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 10.61 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 580 / DUBLIN RD Longitude 82 16 49.22 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other






548 / \$548

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



UNIT #1 WAS TRAVELING WEST ON SEC 564. UNIT #2 WAS TRAVELING EAST ON SEC 564, ATTEMPTING TO TURN LEFT INTO A PRIVATE DRIVE. UNIT #2 FAILED TO YIELD AND WAS STRUCK BY UNIT #1.


Longitue


5 - Spur 9 - Other

17

18.36

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.






S W 2 - Exit

UNITS 1 AND 2 WERE TRAVELING WESTBOUND ON SECONDARY 564. UNIT 1 WAS ATTEMPTING TO TURN LEFT ONTO SHAMROCK LN. FOR UNKNOWN REASONS, UNIT 2 STRUCK THE REAR OF UNIT 1. UNIT 2 LEFT THE SCENE AND REMAINS UNKNOWN.

5 - Spur 9 - Other


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



/ DUBLIN RD

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



UNIT #1 WAS TRAVELING WEST ON S-564. UNIT #2 WAS ATTEMPTING TO CROSS S-564 AT A STOP SIGN. THE DRIVER OF UNIT #2 FAILED TO YIELD RIGHT OF WAY AND WAS STRUCK BY UNIT #1.

Longitude

5 - Spur 9 - Other

15

59.63

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name CAMPBELL, A.P.


Rank CPL

SCCJA# 6338-6726

Jurisdiction Code Review Date HP03 02-15-2021 HP03

Reviewer's Name J R ELROD

Internal Agency Code GVTC21CAD014280 Rank SGT



1142 / CHROME DR

Longitude

5 - Spur 9 - Other

17


31.61


N F 1 - Entrance

S W 2-Exit

N F

S W 3 - SC Primary 6 - Other 7 - Ramp





548 / ROPER MOUNTIAN RD

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F

2 - Alternate 7 - Business


9 - Other

5 - Spur


Longitude

16

42.62




HP03



1142 / CHROME DR

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



Unit # 1 was traveling east on SEC 564. Unit # 2 was stopped on the shoulder of SEC 564. Unit # 2 attempted to make a U-turn onto SEC 564 from the shoulder. Unit # 2 failed to yield to unit # 1. Unit # 2 struck unit # 1 on the front, right side.


Longitude

5 - Spur 9 - Other


17

34.91

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



21220268 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0801 0907 TR-310 (Rev. 04/2016) In Near City or Town of: 0- Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 03-12-2021 0801 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.05 580 , DUBLIN RD 0 s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 15.10 1 - Interstate 4 Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 548 / ROPER MOUNTAIN RD Longitude 82 16 44.58 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other




UNIT #1 WAS ATTEMPTING TO TURN INTO THE MEDIAN ON SEC 564
FROM A PRIVATE DRIVE TRAVELING NORTH. UNIT #2 WAS TRAVELING
EAST ON SEC 564 IN THE MEDIAN. DRIVER OF UNIT #2, DRIVING IN
A MEDIAN, STRUCK THE FRONT LEFT OF UNIT #1 WITH THE CENTER
FRONT.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name

Rank
LCPL
SCCJA#
Jurisdiction Code Review Date
HP03
Reviewer's Name
CJ. LADUE
Reviewer's Name
CPL
GVTC21CAD027718



HOKE SMITH BLVD



UNIT #1 WAS TRAVELING EAST ON SEC.-564 AND THE DRIVER WAS DRIVING UNDER THE INFLUENCE. UNIT #1 RAN OFF OF THE ROADWAY TO THE RIGHT, STRUCK A FENCE LINE, STRUCK A TREE HEAD ON, AND THEN CAUGHT FIRE.

Longitude

5 - Spur 9 - Other

15

50.83

06/08/2021: THIS REPORT WAS CORRECTED TO SHOW THE MOST HARMFUL EVENT FOR UNIT #1.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name D. P. ROBERTSON Rank MTRP SCCJA# 6779-1243

N F 1 - Entrance

S W 2 - Exit


NF

S W 3 - SC Primary 6 - Other 7 - Ramp

Jurisdiction Code Review Date HP03 06-10-2021 HP03

Reviewer's Name CAMPBELL, A.P.

Internal Agency Code GVTC21CAD029515 Rank CPL



385 /

Second Intersection (Rt. # / Name)

1 Interstate 4 - Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp


Τo

F

F 1 - Entrance

S W 2-Exit

R. R. Id



UNIT #1 HAD JUST ENTERED SEC 564 AND BEGAN TRAVELING WEST. UNIT #2 HAD JUST ENTERED SEC 564 AND BEGAN TRAVELING EAST. DRIVER OF UNIT #1 STATED THEY WERE IN THE TURN LANE WHEN CONTACT WAS MADE. DRIVER OF UNIT #2 STATED THEY WERE BOTH IN THE WIDE MEDIAN WHEN CONTACT WAS MADE. DUE TO CONFLICTING STORIES AND NO DEBRIS LEFT IN ROADWAY OR WITNESSES, NEITHER UNIT IS SHOWN AS CONTRIBUTING.

34

Λ

Longitude

Main line 6 - Connection

2 - Alternate 7 - Business

9 - Other


5 - Spur

49


32.42


43.15

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



21222983 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0639 0720 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 03-18-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 NF Miles EGREES MINUTES SECONDS 20 548, ROPER MOUNTAIN RD s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 10.46 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 580 / DUBLIN RD Longitude 16 49.25 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit







5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

16





21227068 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY opy of Original TRAFFIC COLLISION REPORT FORM 1347 1356 (Rev. 04/2016) 2 0-)Main line 6- Connection TR-310 In Near City or Town of: 1 - Interstate 4 Secondary Miles Dir Date Time of County Collision Location (Rt. # / Name) 2- Alternate 7- Business N E 2 - US Primary 5 - County 564/ 04-05-2021 1345 23 0.01 GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction Distance Offset 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Base Intersec ion (Rt # / Name) N E Miles 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 6 N (E) DEGREES MINUTES SECONDS # 3 492 , PELHAM ROAD SW 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other 0 Feet Latitude 34 49 31.64 2 Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id 1 - Interstate 4 - Secondary Ramp Only To From N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N E 1 - Entrance 146 / WOODRUFF ROAD Longitude 82 43.44 5 - Spur 9 - Other S W 2-Exit

Dir. of Travel Unit 1: N S (E) W	Unit 2: N S E W Unit 3: N S E W	7
	<u> 分</u>	UNIT #1 AND UNIT #2 WERE EASTBOUND STOPPED FOR TRAFFIC ON SECONDARY 564. DRIVER OF UNIT #1, MADE AN IMPROPER START FROM A STOP, STRIKING UNIT #2 IN THE CENTER REAR WITH THE CENTER FRONT.
_	UNIT #1 5	
NOTICE - THE TR-310 IS FOR STATISTICA		OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N

Jurisdiction Code Review Date HP03 04-14-2021

HP03

Reviewer's Name
J. T. BUMGARNER


Investigating Officer's Name MOON-T.J.

Rank

SCCJA# 4553-8642

Internal Agency Code GVTC21CAD036179

Rank CPL



21230160 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0926 0930 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 04-16-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 NF Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.08 s (W) s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П Latitude 34 50 8.69 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 1142 / CHROME DR

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2-Exit




5 - Spur 9 - Other

Longitude

16


52.80




UNITS 1 AND 2 WERE BOTH MAKING A RIGHT ONTO S-564 FROM A PRIVATE DRIVE. THE DRIVER OF UNIT 2 MADE AN IMPROPER TURN AND STRUCK UNIT 1.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Internal Agency Code GVTC21CAD040017 Investigating Officer's Name D. P. KUGLER Rank LCPL SCCJA# 7607-1358 Jurisdiction Code Review Date HP03 04-23-2021 Reviewer's Name CAMPBELL, A.P. Rank CPL HP03



21230246 **ORIGINAL - CORRECTED** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1418 1430 X TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 04-09-2021 23 GREENVILLE 564/ 0.1 SW 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of NL Miles NF EGREES MINUTES SECONDS # NL s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 3.41 1 - Interstate 4 - Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To 2 - Alternate 7 - Business 2 - US Primary 5 County N F 1 - Entrance NF / GATEWAY ACCESS ROAD Longitude 17 10.46 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other



Unit # 1 was traveling west on Secondary 564. Traffic was slowing ahead of Unit # 1. Unit # 1 was traveling too fast for conditions. Unit # 1 swerved off the right side of the roadway and struck a utility pole.

Distance offset was added to report on 04-12-2021

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


Investigating Officer's Name J.A. JOHNSON Rank MTRP

S W 2 - Exit

SCCJA# 6500-8107

Jurisdiction Code Review Date HP03 04-18-2021 HP03

Reviewer's Name WARDLAW-JOSEPH C



/ HONBARRIER DRIVE


2 - US Primary 5 County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF



Unit # 1 was stopped on Secondary 564. Unit # 2 was at the traffic light on Secondary 564. Unit # 2 thought he could make the light onto Secondary 492, but traffic was too congested and he was blocking the intersection. Unit # 2 then backed improperly and struck Unit # 1.

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

15


36.68

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name
J.A. JOHNSON

Rank SCCJA# MTRP 6500-8107 Jurisdiction Code Review Date HP03 04-28-2021 Reviewer's Name WARDLAW-JOSEPH C Rank Internal Agency Code GVTC21CAD043823



Second Intersection (Rt. # / Name)

HONBARRIER DR

1 - Interstate 4 - Secondary

2 - US Primary 5 County

S W 3 - SC Primary 6 - Other 7 - Ramp

To


NF

Ramp Only

N F 1 - Entrance

S W 2 - Exit

R. R. Id



Unit #1 was traveling through a green indicated traffic control device signal headed north on Garlinton Rd. Unit #1 then make a left turn onto S-492. Unit #2 was traveling through a red indicated traffic control device signal headed east on S-492. Unit #2 then struck Unit #1 on the driver's side of the vehicle.

Main line 6 - Connection

2 - Alternate 7 - Business


5 - Spur 9 - Other


Longitude


15


22.15

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.










21234241 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0551 0551 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 04-24-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.3 999, HONBARRIER DR s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other П Latitude 34 51 15.55 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / WYNDHAM CT Longitude 15 38.49 S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit



5 - Spur 9 - Other



HP03




21235281 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1728 1751 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NE 2 - US Primary 5 - County 05-06-2021 23 564 / GARLINGTON RD GREER (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 NF EGREES MINUTES SECONDS 10 WYNDHAM CT SW s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 51 9.47 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 1078 / Longitude 15 45.38


5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



HP03



GELSEMIUM PL


2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF



UNIT #1 WAS CROSSING SEC-564 ON SNIPES ROAD NORTH. UNIT #2
WAS TRAVELING WEST ON SEC-564. UNIT #2 DISREGARDED THE
TRAFFIC CONTROL OFFICER. UNIT #2 STRUCK UNIT #1 ON THE RIGHT
FRONT.

2 - Alternate 7 - Business

5 - Spur 9 - Other


0

16

13.67

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



21242776 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1049 1108 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 05-26-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.2 s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 10.32 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF

/ CHROME DR

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit




82

16

49.40


Longitude

5 - Spur 9 - Other



UNIT #1 WAS TRAVELING EAST ON SEC. 564. UNIT #2 FAILED TO YIELD THE RIGHT OF WAY TURNING LEFT ONTO SEC. 564 EAST FROM A DRIVEWAY. UNIT #2 STRUCK THE LEFT SIDE OF UNIT #1 WITH THE

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



Second Intersection (Rt. # / Name)

146 / WOODRUFF RD

1 - Interstate 4 - Secondary

N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp


R. R. Id

Ramp Only

N F 1 - Entrance

S W 2-Exit

To



UNIT #1 WAS FACING WEST ON SECONDARY 564, STOPPED FOR TRAFFIC. UNIT #2 WAS TRAVELING WEST ON SECONDARY 564, TOO FAST FOR CONDITIONS AND STRUCK UNIT #1 IN THE REAR.

Main line 6 - Connection

2 - Alternate 7 - Business


5 - Spur 9 - Other

17

37.57


Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



21255123 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1352 1426 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 07-03-2021 1345 23 564 / GARLINGTON RD GREENVILLE 0.75 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 NF EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 40 s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Feet Latitude 34 50 10.97 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only N E 2 - US Primary 5 County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N F 1 - Entrance / DUBLIN RD Longitude 82 16 48.87 5 - Spur 9 - Other






S W 2 - Exit

UNIT#1 WAS ATTEMPTING TO TURN LEFT FROM S 564 ONTO S 548. UNIT#2 WAS TRAVELING WEST ON S 564, STRUCK UNIT#1 IN THE RIGHT REAR SIDE, AND THEN LEFT THE SCENE.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



g Second Intersection (Rt. # / Name)

999 / HOMBARRIER DR

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

Λ

15

22.25

Longitude

1 - Interstate 4 Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp


To


N F

N F 1 - Entrance


S W 2-Exit

R. R. Id






21259056 ORIGINAL - AMENDED SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1046 1113 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 07-17-2021 23 GREENVILLE 564 / GARLINGTON RD SW 3 - SC Primary 6 - PP 7 - Ramp 5- Spur Main line 6 - Connection Direction 1 - Interstate GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of NF Miles EGREES MINUTES SECONDS 0.2 WYNDHAM CT NL S (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 51 9.40 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary (5) County N F 1 - Entrance NF / HARTNESS DR Longitude 15 45.43 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit




UNIT #1 WAS TRAVELING WESTBOUND ON SECONDARY 564. UNIT #1, DRIVING TOO FAST FOR CONDITIONS, LEFT THE THE ROADWAY TO THE RIGHT AND STRUCK A POST WITH THE RIGHT FRONT OF UNIT #1. UNIT #1 THEN CONTINUED FORWARD AND STRUCK A CABLE POST WITH THE RIGHT FRONT OF UNIT #1. THE PROPERTY OWNER INFORMATION FOR THE POST IS UNKNOWN AND THE HOA PRESIDENT HAS NOT CONTACTED US AT THIS TIME TO PROVIDE THAT INFORMATION.

AMENDED 7/23/2021 TO SHOW OWNERSHIP OF POST THAT WAS STRUCK.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.




21260880 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1620 1710 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N E 07-21-2021 1615 23 564 / GARLINGTON RD GREENVILLE S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 5 EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 30 s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 10.18 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 1142 / CHROME DR Longitude 16 49.62 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit



UNIT 1 WAS STOPPED FACING EAST ON SEC 564. UNIT 2 WAS
TRAVELING EAST ON SEC 564. THE DRIVER OF UNIT 2, DRIVING TOO
FAST FOR THE CONDITIONS, STRUCK UNIT 1 WITH UNIT 2, CAUSING
DAMAGE TO THE MIRROR OF UNIT 1.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit



Unit 1 was traveling east from a private drive attempting to turn north onto Garlington Road across a paved median. paved median was marked to indicate it was clearly not designed for travel. Unit 2, traveling south on Garlington Road in said paved median, while passing stopped traffic, was attempting to turn east into a private drive. Unit 1 struck the right side of unit 2. Unit 2 was cited for driving in a lane not designed for travel.

16

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit

Longitude


5 - Spur 9 - Other

15

22.14




HP03




5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2-Exit






21274626 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1922 1934 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 09-26-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 NF Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.05 s (M) s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П Latitude 34 50 8.89 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary (5) County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF / CHROME DR Longitude 16 52.31 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other





UNIT 1 AND UNIT 2 WERE TRAVELING WEST ON SEC-564. UNIT 2 MADE AN IMPROPER U-TURN AND STRUCK THE PASSENGER SIDE OF UNIT 1.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



g Second Intersection (Rt. # / Name)

/ CARRIE DR

Main line 6 - Connection

2 - Alternate 7 - Business


5 - Spur 9 - Other

0

16

13.98

Longitude



1 - Interstate 4 - Secondary

S W 3 - SC Primary 6 - Other 7 - Ramp

2 - US Primary (5) County

To

NF

Ramp Only


N F 1 - Entrance

S W 2 - Exit

R. R. Id

UNIT #1 WAS TRAVELING EAST ON SECONDARY 564. UNIT #2 WAS FACING NORTH ON SNIPES ROAD. UNIT #2 FAILED TO YIELD AND STRUCK UNIT #1 ON THE PASSENGER SIDE FRONT.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.





21276364 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1121 1133 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business NE 09-21-2021 23 GREENVILLE 564 / GARLINGTON ROAD (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.14 580, DUBLIN ROAD 0 s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 12.05 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 548 / ROPER MOUNTAIN RD Longitude 16 47.57 S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



5 - Spur 9 - Other





g Second Intersection (Rt. # / Name)

/ HARTNESS DR

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

Λ

Internal Agency Code GVTC21CAD106389

Rank CPL

15

50.14

Longitude

1 - Interstate 4 - Secondary

S W 3 - SC Primary 6 - Other 7 - Ramp

2 - US Primary 6 County

To

N F

Ramp Only

N F 1 - Entrance


S W 2-Exit

R. R. Id

Investigating Officer's Name J. C. OWENS

Rank TPR


SCCJA# 4573-1328



Jurisdiction Code Review Date HP03 09-19-2021


HP03


Reviewer's Name CD TERRY



21280942 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1151 1221 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NF 2 - US Primary 5 - County 10-01-2021 23 564 / GARLINGTON RD GREENVILLE s W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 NF Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.03 s (M) s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П Latitude 34 50 9.76 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only N E 2 - US Primary (5) County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N F 1 - Entrance / CHROME DR Longitude 16 50.74 S W 2-Exit 5 - Spur 9 - Other









5 - Spur 9 - Other

S W 2 - Exit





/ DUBLIN RD


2 - US Primary 6 County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F



UNIT #1 WAS TRAVELING EAST ON SEC 564. UNIT #2 WAS TRAVELING WEST ON SEC 564. DRIVER OF UNIT #2, DRIVING LEFT OF CENTER, STRUCK THE CENTER FRONT OF UNIT #1 WITH THE FRONT RIGHT.

2 - Alternate 7 - Business

5 - Spur 9 - Other


Λ

15

57.96

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.




21284694 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1744 1916 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N E 10-14-2021 23 564 / GARLINGTON RD GREENVILLE s w 6-PP 7-Ramp 5- Spur 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N E 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.2 CARRIE DR s 🐠 3 - SC Primary 6 - Other 7 - Ramp s w 5 - Spur 9 - Other O Latitude 34 50 25.22 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To 2 - US Primary 6 County 2 - Alternate Λ N F 1 - Entrance N F siness / SNIPES RD Longitude 30.62


5 - Spur


S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2-Exit

16








S W 2-Exit


Unit 1 was traveling west on Sec-564. Unit 2 was turning right from a driveway onto Sec-564 west and failed to yield the right of way, striking unit 1 on the right side.


5 - Spur 9 - Other

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.




21286206 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 2047 2131 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 10-18-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of NF EGREES MINUTES SECONDS # NL 548, ROPER MOUNTAIN RD s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 10.07 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / TAMMY RAY DR Longitude 16 49.27 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other






21291666 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1226 1238 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of County 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 10-31-2021 23 564 / GARLINGTON RD GREENVILLE 0.01 (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 DEGREES MINUTES SECONDS 1142 / CHROME DR 50 s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur SW Eeet 9 - Other Latitude 34 49 56.32 1 Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N E 1 - Entrance NF 385 / 1385 Longitude 17 31.34 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other





HP03




21294024 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0139 0251 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 11-07-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business NF Miles Of EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.05 NL s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 9.22 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 1112 / CHROME DR Longitude 16 51.67

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit



5 - Spur 9 - Other



HP03



21294844 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1433 1506 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 11-09-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business NF Miles Of EGREES MINUTES SECONDS # NL 0.5 1078 , (UNNAMED RD) s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 51 5.43 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary (5) County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

/ HARTNESS DR





5 - Spur 9 - Other


Longitude

15

47.12








S W 2 - Exit


UNIT #1 WAS STOPPED EAST ON SEC.-564 WAITING TO TURN LEFT. UNIT #2 WAS TRAVELING TOO FAST FOR CONDITIONS EAST ON SEC.-564 AND THE DRIVER WAS INATTENTIVE LOOKING AT SOMETHING INSIDE UNIT #2. UNIT #2 STRUCK UNIT #1 IN THE REAR END WITH THE FRONT END OF UNIT #2.

5 - Spur 9 - Other

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT N WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.




21450060 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 0752 0950 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2 - US Primary 5 - County 2- Alternate 7- Business N (E) 11-09-2021 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.01 **GATEWAY ACCESS RD** s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 3.41 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / CHROME DR Longitude 17 10.46 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit



UNIT #1 WAS STOPPED EAST ON SEC.-564 AFTER HAVING JUST BEEN INVOLVED IN A COLLISION. UNIT #2 WAS TRAVELING TOO FAST FOR CONDITIONS EAST ON SEC.-564 AND THE DRIVER WAS INATTENTIVE LOOKING AWAY FROM THE ROADWAY. UNIT #2 STRUCK UNIT #1 IN THE REAR END WITH THE FRONT END OF UNIT #2. THE DRIVER OF UNIT #2 WAS UNABLE TO PROVIDE HER PHONE NUMBER.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



/ GELSEMIUM PL

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

16

13.06

Longitude


2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp


N F 1 - Entrance

S W 2 - Exit

NF



HP03



1142 / CHROME DR

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit


Longitude

5 - Spur 9 - Other

17

29.72






ORIGINAL 21454690 SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY opy of Original TRAFFIC COLLISION REPORT FORM 1553 1726 (Rev. 04/2016) 4 ①-Main line 6- Connection TR-310 In Near City or Town of: 1 - Interstate 4 Secondary Miles Dir Date Time of County Collision Location (Rt. # / Name) 2- Alternate 7- Business N E 2 - US Primary 5 - County 564 / GARLINGTON RD 11-22-2021 1550 23 **GREENVILLE** s w 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) 2 - US Primary 5 County 3 - SC Primary 6 - Other 7 - Ramp N (E) Miles 2 - Alternate 7 - Business Of 2 ΝE DEGREES MINUTES SECONDS 0.01 , CHROME DR 1 s (W) s w 5 - Spur 9 - Other O ш Latitude 34 49 59.23 Main line 6 - Connection R. R. Id 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Ramp Only To N E 2 - US Primary 5 - County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N E 1 - Entrance 1142 / CHROME DR Longitude

S W 2-Exit


5 - Spur 9 - Other

29.72

Dir. of Travel	Unit1:NSEW	Unit 2:	NSEW	Unit 3: N S E	W						
					Ļ						
					-		#1 AND UNIT#2				
							‡3 WAS SLOWING ELING WEST ON				54. UNIT#4 WAS
							ITIONS, STRUCK		-		
							CK UNIT#1.	011271137 01		tock olderne	. Online
NOTICE THE TO 2	AA IS FOR STATISTICA	L DEDODTIN	IC DUDDOSES ON	LV AND IS A DEFLI	CTION OF	THE C	AFFICEDIE DEET KNO	WILEDGE ODIN	HON AND DE	LIEE COVERNO	THE COLLISION DUT N
	E AS THE FACTUAL A			LY AND IS A REFLE	CHONOF	THE	PERICER'S BEST KNO	WLEDGE, OPIN	IION AND BE	LIEF COVERING	THE COLLISION BUT N
Investigating Office	er's Name	Rank	SCCJA#	Jurisdiction Code			Reviewer's Name		Rank	Internal Agen	cy Code
DILWOŘTH, J. P.		TPR	9800-1119	HP03	12-02-2021		CAMPBELL, A.P.		CPL	GVTC21CA	D133189




21455684 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1054 1124 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business (N) E 2 - US Primary 5 - County 11-25-2021 23 564 / GARLINGTON ROAD GREENVILLE S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 NF Miles EGREES MINUTES SECONDS 0.23 HARTNESS DR s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 51 13.15 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To 2 - US Primary 5 - County 2 - Alternate 7 - Business N E N F 1 - Entrance 492 / PELHAM ROAD Longitude 82 15 40.94 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other



UNIT #1 WAS WESTBOUND ON SECONDARY 564. A DEER RAN INTO THE PATH AND STRUCK THE CENTER FRONT.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



999 / HONBARRIER DR


2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF



UNIT 1 WAS TRAVELING NORTH ON S564 AND WAS STOPPED FOR TRAFFIC. UNIT 2 WAS TURNING LEFT ONTO S564 FROM A PRIVATE DRIVE WITH LIGHTS AND SIRENS. THE DRIVER OF UNIT 2 WHILE ATTEMPTING TO CROSS S564 MADE AN IMPROPER START FROM STOP AND STRUCK THE REAR OF UNIT 1. NO CITATION ISSUED.

2 - Alternate 7 - Business

5 - Spur 9 - Other


0

15

23.14


Longitude


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NOW WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.





S W 2 - Exit


5 - Spur 9 - Other











ORIGINAL SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA #Of mended - Attach Copy Notified Arrived age # of Original Report Units TRAFFIC COLLISION REPORT FORM 1351 1415 (Rev. 04/2016) 02 TR-310 Main Line - Interstate Collision Location (Rt. # / Name) Dir. (In) Near City or Town of: 2021506334 Collision 2- US Primary 5-County 2-Alternate ΝE 7-Business € 564 GREENVILLE 02-06-2021 1346 / GARLINGTON RD 3- SC Primary 6-PP 7-Ramp S W GPS COORDINATES 00 00' 00.00" 0-Main Line Lane # / Dir 1- Interstate Base Intersection (Rt. # / Name) 6-Connection ND 2- US Primary 5- County 2-Alternate 7-Business **DEGREES MINUTES SECONDS** Miles

/ WOODRUFF RD

Second Intersection (Rt. # / Name)

9-Other

6-Connection

7-Business

Latitude

Longitude

49

5-Spur

0-Main Line

2-Alternate

146

3-SC Primary 6-Other 7-Ramp

1-Interstate 4-Secondary

2- US Primary County

.03

From

R.R. Id.


Feet


Ramp Only

N E 1- Entrance


SW


To








		UKI	GINAL	-											
	SOUTH CAROLINA DPS/OHS & DMV USE ONLY			P 1	Page # SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)			# Of Units 5) 02	Amended - Att of Original Rep Corrected		Notified 1 6 0 1	Arrive	ed 6 1 0		
12		Collision 1 6 0 0 23	1- Intersta 2- US Prin 3- SC Prin	mary	Secondary 5- County 6- PP 7- Ram	Manage and the second	ocation (Rt. # / Name) GARLINGTON RD	0-Main Line 6-Con 2-Alternate 7-Busi 5-Spur	nnection Mil siness	ΝE	GREEN	Near City or T	own of:	•	
1215	Lane # / Dir. # Of N		0.000	N (D)	1- Interstate 2- US Primary		Ę 2-		A STATE OF THE STATE OF	Alter Andrewsking and an		PS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS			
202	1 6 S (Feet Samp Only	S W (6-Other 7-Ramp Secondary	Second Intersection (R	,	20,000	9-Other 6-Connection	Latitude	34	49	32.91	
	i	N E 1-1	Entrance	ΝE	2- US Primary	5- County	war	2-	-Alternate	7-Business	Longitude	0	10	11	












ORIGINAL SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA #Of mended - Attach Copy Notified Arrived of Original Report Units TRAFFIC COLLISION REPORT FORM 2145 2155 (Rev. 04/2016) 02 TR-310 Interstate Collision Location (Rt. # / Name) Dir. (In) Near City or Town of: Collision 2- US Primary 5- County ΝE 2-Alternate 7-Business / GARLINGTON RD GREENVILLE 06-23-2021 2145 ⊆ 564 6-PP 7-Ramp 3- SC Primary s w GPS COORDINATES 00 00' 00.00" Lane # / Dir 1-Interstate (4)Secondary Base Intersection (Rt. # / Name) 0-Main Line 2- US Primary 5- County 2-Alternate 7-Business **DEGREES MINUTES SECONDS** Miles 548 / ROPER MOUNTAIN RD S W 3-SC Primary 6-Other 7-Ramp SW Feet 5-Spur 9-Other Latitude R.R. Id. 1- Interstate 4 Secondary Ramp Only To Second Intersection (Rt. # / Name) 0-Main Line 6-Connection From 50 00.20


2-Alternate


7-Business


Longitude


2- US Primary 5- County













ORIGINAL-CORRECTED

ALBRIGHT - J W

PO2

3587-3116






2 3 0 2 08-25-2021

OHS 94


POIII

21-048749



GABRIELE - M A

		U	KIGINA	4L										
	SOUTH CAROLINA DPS/OHS & DMV USE ONLY					Page # SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)			# Of Units 16) 02	Amended - A of Original R Corrected		Notified 1 5 2 8	Arrive	d 3 7
49258	Date 08-04-2021	Time of Collision		erstate (Primary Primary	Secondary 5- County 6- PP 7- Ran	Wester Brown Christia	Location (Rt. # / Name) GARLINGTON RD	The second secon	onnection Mil Jusiness	es: Dir. N E S W	GREEN	Near City or	Town of	
20215	Lane # / Dir.	E	nce Offset Miles	N (E)	2- US Primary	4- Secondary 5- County	Base Intersection (Rt. # / Name)			6-Connection 7-Business	GPS COORDINATES 00 00' 00.00" DEGREES MINUTES SECO			
8	1 6 S	.02 From	Ramp Only			6- Other 7- Ramp	p ≥ 146 / WOODRU		0.503,000	9-Other 6-Connection	Latitude	34	49	31.91
- 1			1- Entrance	ΝE	2- US Primary	5- County	war	200 200	2-Alternate	7-Business	Longitud	0	E	11



2 3 0 2 08-05-2021


Skyler Queen

POIII

21-053338

PO III


1519-8613




BREEDEN - C J

PO₃

5698-4666








Skyler Queen


POIII


21-058615



















ORIGINAL


ORIGINAL				
SOUTH CAROLINA DPS/OHS & DMV USE ON	Page # SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)	# Of Units Amended - of Original F		Arrived
Date		nection Miles: Dir. ness N E S W	(In) Near City or GREENVILLE	Town of:
Lane # / Dir. Distance Offset Direct	2-US Primary 5-County E	Main Line 6-Connection Alternate 7-Business	GPS COORDINATES 00 DEGREES MINU	
Of N E Miles N (1 3 5 (M) 16 Feet S V R.R. id. From Ramp Only T	1-Interstate 4- Secondary Second Intersection (Rt. # / Name)	Spur 9-Other Main Line 6-Connection	Latitude 34	49 33.44
N E 1- Entrance N	2- US Primary 5- County	Alternate 7-Business	Longitude	1 11







ORIGINAL


ORIGINAL			
SOUTH CAROLINA DPS/OHS & DMV USE ONLY	Page # SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM TR-310 (Rev. 04/2016)	Units of Original F	Attach Copy Rotified Arrived Report 1 2 2 0 1 2 2 5
Date		nection Miles: Dir. N E S W	(In) Near City or Town of: GREENVILLE
	ary 5-County E 2-A	Main Line 6-Connection Alternate 7-Business	GPS COORDINATES 00 00' 00.00" DEGREES MINUTES SECONDS
R.R. Id. From Ramp Only To 1-Interst	ary 6-Other 7-Ramp 2 146 / WOODRUFF RD 5-S te 4-Secondary 2 Second Intersection (Rt. # / Name)	pur 9-Other Main Line 6-Connection	Latitude 34 49 33.20
N E 1- Entrance N E 2- US Prir		Alternate 7-Business	Lonaitude 0 1 11





ORIGINAL





2 3 0 2 11-18-2021

Skyler Queen


POIII

21-080419

PO3

BROWN - P J

0807-2574



ORIGINAL-CORRECTED SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA #Of mended - Attach Copy Notified Arrived age # of Original Report Units TRAFFIC COLLISION REPORT FORM 1407 1424 02 (Rev. 04/2016) TR-310 507 - Interstate Collision Location (Rt. # / Name) Dir. In Near City or Town of: Collision 2- US Primary 5- County ΝE 2-Alternate 7-Business GREENVILLE 12-06-2021 1359 564 / GARLINGTON RD 2021581 6-PP 7-Ramp 3- SC Primary s w GPS COORDINATES 00 00' 00.00" Lane # / Dir 1-Interstate Base Intersection (Rt. # / Name) 0-Main Line ND 2- US Primary 5- County 2-Alternate 7-Business **DEGREES MINUTES SECONDS** Miles

/ WOODRUFF RD

Second Intersection (Rt. # / Name)

5-Spur

0-Main Line

2-Alternate

9-Other

6-Connection

7-Business

Latitude

Longitude

49

33.06

Fron

3 SC Primary 6-Other 7-Ramp

1-Interstate 4- Secondary

2- US Primary 5- County

146

.06

rom


R.R. Id.


Feet

Ramp Only

SW

To





ORIGINAL-CORRECTED SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA #Of mended - Attach Copy Notified Arrived age # of Original Report Units TRAFFIC COLLISION REPORT FORM 2016 2038 1 (Rev. 04/2016) 02 TR-310 ain Line - Interstate Collision Location (Rt. # / Name) Dir. In Near City or Town of: 2021586382 Collision 2- US Primary ΝE 5-County 2-Alternate 7-Business GREENVILLE 12-21-2021 2006 564 / GARLINGTON RD 3- SC Primary 6-PP 7-Ramp s w GPS COORDINATES 00 00' 00.00" Lane # / Dir 1- Interstate Base Intersection (Rt. # / Name) 0-Main Line NO 2- US Primary 5- County 2-Alternate 7-Business **DEGREES MINUTES SECONDS** Miles 년 146 .00 / WOODRUFF ROAD Feet SW 3 SC Primary 6-Other 7-Ramp 5-Spur 9-Other

Second Intersection (Rt. # / Name)

1- Interstate 4 Secondary

2- US Primary 5- County

R.R. Id.

Ramp Only

From

To

Latitude

Longitude

49


30.94


0-Main Line

2-Alternate

6-Connection

7-Business







22200000 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1811 1831 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 01-05-2022 23 564 / ROPER MOUNTAIN RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 5 NF Miles EGREES MINUTES SECONDS **GARLINGTON RD** 0.07 3 s (W) s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 10.30 1 - Interstate 4 - Secondary 2 Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / SNIPES RD S W 3 - SC Primary 6 - Other 7 - Ramp Longitude 16 45.88 5 - Spur 9 - Other

S W 2 - Exit









22203324 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM py of Original 1724 1801 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NE 2 - US Primary 5 - County 01-06-2022 23 564 / ROPER MOUNTAIN RD GREENVILLE (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 NF Miles EGREES MINUTES SECONDS GARLINGTON RD 0.07 s (W) s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 8.47 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 1142 / CHROME DR Longitude 16 53.01 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other









5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit





22211747 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM of Original Report 1610 1633 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N E 2 - US Primary 5 - County 02-03-2022 23 GREENVILLE 564 / \$564 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 1142 / \$1142 SW 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 49 52.37 1 Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF

385 / 1385

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit




17


31.54

Longitude

5 - Spur 9 - Other



HP03



ORIGINAL 22211747 SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY Amended - Attach Cop of Original Report TRAFFIC COLLISION REPORT FORM 1610 1633 (Rev. 04/2016) 4 ①-Main line 6- Connection TR-310 In Near City or Town of: 1 - Interstate 4 Secondary Miles Dir Date Time of Collision Location (Rt. # / Name) 2- Alternate 7- Business N E 2 - US Primary 5 - County 02-03-2022 1600 23 **GREENVILLE** 564 / \$564 s w 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) 2 - US Primary 5 - County 3 - SC Primary 6 - Other 7 - Ramp N (E) Miles 2 - Alternate 7 - Business Of 2 DEGREES MINUTES SECONDS 0.1 1142 / S1142 s w s w 9 - Other 5 - Spur O ш Latitude 34 49 52.37 Main line 6 - Connection R. R. Id 1 Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Ramp Only To N E 2 - US Primary 5 - County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N E 1 - Entrance

385 / 1385

S W 2-Exit




5 - Spur 9 - Other

Longitude


17

31.54

Dir. of Travel	Unit 1: N S E W	Unit 2:	NSEW	Unit 3: N S E	W					
					U	JNIT	#1 THROUGH #3 WERE	ALL	TRAVELING	EAST ON SEC 546, STOPPED
					F	OR 1	RAFFIC. UNIT #4 WAS	5 TRA	VELING EA	ST ON SEC 546. THE DRIVER
					0	OF UN	IIT #4, DRIVING TOO	FAST	FOR COND	OITIONS, STRUCK UNIT #3.
					UI	JNIT	#3 THEN STRUCK UNI	Г#2,	WHICH ST	RUCK UNIT #1.
	NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.									
Investigating Of J.M. BALLISH	icer's Name	Rank LCPL	SCCJA# 1029-6972	Jurisdiction Code	Review Da 02-04-2022		Reviewer's Name CD TERRY		Rank CPL	Internal Agency Code
J.M. BALLISH		LCPL	1029-0912	HP03	02-04-2022	l'	CDIERRI		CPL	GVTC22CAD012319




SOUTH CAR	ROLINA E	PS/OHS 8	R DMV USE O	NLY Pag	Of: 1	SOUTH CARO TRAFFIC COLLISION R TR-310		# Of Units 016) 2	of	nended - A Original R orrected	attach Copy Not eport	2025	Arrive	2035
Date 02-19-2022	Time of Collision 2024	23 2	- Interstate - US Primary - SC Primary	4 Secondary 5 - County 6 - PP 7 - Ramp	ESA . CA	ocation (Rt. # / Name)	Main line 6- 2- Alternate 7- 5- Spur		Miles 1	Dir. N (E) S W		Near City or	Town of:	
Lane#/Dir # Of N (1 2 S	D 0.	03	iles N (E)	1 - Interstate 4 2 - US Primary 5 3 - SC Primary 6	- County	Base Intersec ion (I		Main lin 2 - Alterna 5 - Spur		ness		RDINATES 00 GREES MINUT		NDS
R. R. Id	From		Only To	1 - Interstate 4) Secondary	© Second Intersection 1142 / CHROME DR		Main lin	e 6 - Con	nection	_atitude	34	50	1.16



Unit #1 was traveling east on S564. Unit #2 was traveling south on a private drive. Unit #2 then failed to yield the right of way and made a left turn on to S564. Unit #1 then struck Unit #2 on the passenger side of the vehicle.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

HOKE SMITH BLVD



Unit #1 was traveling west on S-564. Unit #2 was stopped at a stop sign headed north on Snipes Rd. Unit #2 then failed to yield the right and attempted to make a left turn. Unit #2 then struck Unit #1 on the driver's side of the vehicle.


Longitude

5 - Spur 9 - Other

16

13.85

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



22216865 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1903 1923 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2 - US Primary 5 - County 2- Alternate 7- Business N E 02-22-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 NF Miles EGREES MINUTES SECONDS 0.03 548, ROPER MOUNTAIN RD s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П Latitude 34 50 9.77 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 -0 2 - US Primary 5 - County N F 1 - Entrance NF 1112 / CHROME DR Longitude 50.63


5 - Spur


9 -

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

16





g Second Intersection (Rt. # / Name)

/ CHROME DR

1 - Interstate 4 - Secondary

S W 3 - SC Primary 6 - Other 7 - Ramp

2 - US Primary 5 County

R. R. Id


Ramp Only

N F 1 - Entrance

S W 2-Exit

To

NF



Unit 1 was traveling east on Sec-564, under the influence, and ran off the road to the right. Unit 1 then struck a traffic sign and light pole.

Latitude

Longitude

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

34

0


50


16


8.03

55.62

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.









22221837 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1303 1335 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business (N) E 2 - US Primary 5 - County 03-11-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp 1 Interstate 4 - Second 2 - US Primary 5 - County Direction Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - Alternate 7 - Business Of 3 Miles NF EGREES MINUTES SECONDS 0.2 385 s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 49 43.72 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / CHROME DR Longitude 17 37.57 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other









22221890 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 0620 0732 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 03-25-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.14 1112 , CHROME DR s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 50 5.17 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 548 / ROPER MOUNTAIN RD Longitude 17 20.97 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other







ORIGINAL - CORRECTED 22222353 SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY Amended - Attach Cop of Original Report TRAFFIC COLLISION REPORT FORM 1240 1300 X (Rev. 04/2016) 2 ①-Main line 6- Connection TR-310 In Near City or Town of: 1 - Interstate 4 Secondary Miles Dir Date Time of County Collision Location (Rt. # / Name) Collision 2- Alternate 7- Business **€** 2 - US Primary 5 - County 564 / GARLINGTON RD 03-10-2022 23 0.01 GREENVILLE S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction Distance Offset 1 - Interstate 4 - Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Base Intersec ion (Rt # / Name) Miles N E 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 6 NE DEGREES MINUTES SECONDS 0.01 146 , WOODRUFF RD 4 s (W) SW 3 SC Primary 6 - Other 7 - Ramp 9 - Other 5 - Spur 0 Feet Latitude 34 49 31.40 Main line 6 - Connection R. R. Id 1 - Interstate 4 Secondary Second Intersection (Rt. # / Name) Ramp Only To N E 2 - US Primary 5 - County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N E 1 - Entrance 1142 / CHROME DR Longitude 17 43.66 S W 2 - Exit 5 - Spur 9 - Other

Dir. of Travel	Unit 1: N S E W Unit 2: N S E W Unit 3: N S	EW	
3	UNIT #1 UNIT #2		
ii)			UNIT # 1 AND UNIT # 2 WERE STOPPED IN TRAFFIC ON SEC 564. UNIT # 2 MADE AN IMPROPER START FROM STOP AND STRUCK UNIT # 1 ON THE REAR.
200			4-15-2022: CORRECTED TO SHOW THE PROPER STATE FOR UNIT # 2.
ž.	SEC 564		
	TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A R IS MADE AS THE FACTUAL ACCURACY THEREOF.	EFLECTION O	F THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT

Jurisdiction Code Review Date HP03 04-15-2022

HP03

Reviewer's Name M.A. FRANKS


Investigating Officer's Name C.L. LEE

Rank

SCCJA# 6976-8436

Internal Agency Code GVTC22CAD027095


Rank SGT




5 - Spur 9 - Other

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit



HP03



g Second Intersection (Rt. # / Name)

/ GELSEMIUM PL

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

Λ

15

48.13

Longitude

1 - Interstate 4 - Secondary

2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp


To

N F

Ramp Only

N F 1 - Entrance


S W 2-Exit



UNIT #1 WAS TRAVELING TOO FAST FOR CONDITIONS WEST ON SEC.-564
AND THE DRIVER WAS INATTENTIVE LOOKING AT HER GPS. THE DRIVER
OF UNIT #1 WAS GOING TO MISS THE TURN FOR DUBLIN ROAD AND HIT
THE BRAKES HARD ATTEMPTING TO TURN ONTO DUBLIN ROAD. UNIT #1
SLID OFF OF THE ROADWAY TO THE RIGHT AND STRUCK A STOP SIGN
WITH ITS FRONT END AND UNDER CARRIAGE.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


R. R. Id



22227118 **ORIGINAL** SOUTH CAROLINA DPS/OHS & DMV USE ONLY SOUTH CAROLINA TRAFFIC COLLISION REPORT FORM of Original Report 2048 2226 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection 1 - Interstate 4 Secondary Miles Dir 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 03-30-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business NF Miles Of # NL 1142 / CHROME DR 0.01 s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 49 56.31 1 Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) 2 - Alternate 7 - Business 2 - US Primary 5 - County N F 1 - Entrance NF 385 / 1385 Longitude 31.60 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other







/ CARRIE DR

2 - Alternate 7 - Business

9 - Other

5 - Spur

Λ

16

14.08

Longitude


2 - US Primary 6 County


S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F





22238144 **ORIGINAL - CORRECTED** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM of Original Report 0007 0012 X TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 05-07-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 NF DEGREES MINUTES SECONDS 20 **DUBLIN RD** s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 16.54 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

548 / ROPER MOUNTAIN RD




5 - Spur 9 - Other

Longitude

16

42.81




Unit 1 was traveling west on Sec-564. Unit 2 was traveling south on Dublin Rd, too fast for conditions, and didn't stop at the stop sign, causing unit 2 to strike unit 1 on the right front corner. Unit 1 then overturned in the roadway.

06/13/22 - Corrected Unit 1 override information.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Internal Agency Code GVTC22CAD051506 Investigating Officer's Name A. D. ELLER Rank TFC SCCJA# 7362-4249 Jurisdiction Code Review Date HP03 06-13-2022 Reviewer's Name CD TERRY Rank CPL HP03



/ HOKE SMITH BLVD

2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F

2 - Alternate 7 - Business

9 - Other


5 - Spur

Λ


15

59.65

Longitude



HP03



22240091 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY Amended - Attach Cop of Original Report TRAFFIC COLLISION REPORT FORM 1846 2003 (Rev. 04/2016) 2 ①-Main line 6- Connection TR-310 In Near City or Town of: 1 - Interstate 4 Secondary Miles Dir Date Time of Collision Location (Rt. # / Name) Collision 2- Alternate 7- Business N E 2 - US Primary 5 - County 05-17-2022 1830 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) # 3 N (E) Miles NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 5 DEGREES MINUTES SECONDS 448 , ROPER MOUNTAIN RD 0.01 s @ SW 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other 0 Latitude 34 50 10.18 Main line 6 - Connection R. R. Id 1 - Interstate 4 - Secondary Second Intersection (Rt. # / Name) Ramp Only To N E 2 - US Primary 5 County S W 3 - SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N E 1 - Entrance / CHROME DR Longitude 16 49.62 5 - Spur 9 - Other S W 2-Exit



				
MEDIAN				
	T			
UNIT#1	<u>UNIT #2</u>			
	小			
	MEDIAN UNIT#1	<u> </u>	IMPROPERLY STARTED	IMPROPERLY STARTED FROM A STOP AND STRUCK

Jurisdiction Code Review Date HP03 05-18-2022

HP03

Reviewer's Name CD TERRY


Investigating Officer's Name KL POWELL

Rank TPR

SCCJA# 8278-8915

Internal Agency Code GVTC22CAD055599

Rank CPL




22242950 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM of Original Report 1158 1223 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N E 2 - US Primary 5 - County 05-23-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 NF Miles EGREES MINUTES SECONDS 0.13 WYNDHAM CT s (W) s w 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 51 13.74 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF GREENVIEW DR Longitude 15 41.15

5 - Spur 9 - Other


S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit







HP03



22244035 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM of Original Report 0757 0803 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NE 2 - US Primary 5 - County 06-07-2022 23 GREENVILLE 564 / GARLINGTON RD (S) W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 3 Miles EGREES MINUTES SECONDS 0.06 CHROME DR s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 49 54.20 1 - Interstate 4 - Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To 2 - Alternate 7 - Business 2 - US Primary 5 - County N F 1 - Entrance NF 146 / WOODRUFF RD Longitude 17 31.66 S W (3) SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other








Second Intersection (Rt. # / Name)

999 / HONBARRIER DR

1 - Interstate 4 Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp



Unit #1 and Unit #2 were stopped due to traffic headed east on S-564. Unit #2 then made an improper start from a stop and struck Unit #1 on the rear of the vehicle.

Latitude

Longitude

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

34

0

51

15

25.16

22.75

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

R. R. Id


Ramp Only

N F 1 - Entrance

S W 2-Exit

To

NF



g Second Intersection (Rt. # / Name)

HONBARRIER DR

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

15

45.14

Longitude

1 - Interstate 4 - Secondary

S W 3 - SC Primary 6 - Other 7 - Ramp

2 - US Primary 5 County

To


NF

Ramp Only

N F 1 - Entrance


S W 2 - Exit

R. R. Id



UNIT 1 WAS TRAVELING EAST ON S-23-564. DRIVER OF UNIT 1 THEN SWERVED TO AVOID A DEER WHICH RAN ONTO THE ROADWAY. UNIT 1 RAN OFF ROAD RIGHT AND STRUCK THE GUARDRAIL END.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2 - Exit

GELSEMIUM PL



UNIT#1 WAS TRAVELING EAST ON SEC. 564. UNIT#2 WAS ATTEMPTING TO TURN ONTO SEC. 564. FOR UNKNOWN REASONS, UNIT#2 TURNED INFRONT OF UNIT#1. UNIT#1 THEN RAN OFF THE ROADWAY TO THE RIGHT AND STRUCK A FIRE HYDRANT. UNIT#2 THEN LEFT THE SCENE. NO CONTACT WAS MADE BETWEEN UNIT#1 AND UNIT#2.

Longitude

5 - Spur 9 - Other

15

51.02

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name DILWORTH, J. P.


Rank TPR

SCCJA# 9800-1119

Jurisdiction Code Review Date HP03 06-10-2022 HP03


Reviewer's Name CAMPBELL, A.P.


Internal Agency Code GVTC22CAD065421 Rank CPL



22247349 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 0957 1031 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Collision 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 06-09-2022 23 564 / GARLINGTON RD GREENVILLE 0.05 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 - Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) Miles NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 DEGREES MINUTES SECONDS 0.04 CHROME DR s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 49 55.01 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To N E 2 - US Primary 5 - County S W (3) SC Primary 6 - Other 7 - Ramp 2 - Alternate 7 - Business 0 N F 1 - Entrance 146 / WOODRUFF RD Longitude 17 31.64 S W 2-Exit 5 - Spur 9 - Other









22250827 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 0727 0738 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N E 2 - US Primary 5 - County 06-30-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 NF Miles DEGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.08 s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 13.05 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id Ramp Only To g Second Intersection (Rt. # / Name) 2 - Alternate 7 - Business 0 N E 2 - US Primary 5 - County N F 1 - Entrance 580 / DUBLIN RD Longitude 16 46.94 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other







1112 / CHROME DR

g Second Intersection (Rt. # / Name)

1 - Interstate 4 Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp


To

N F

N F 1 - Entrance

S W 2-Exit

R. R. Id



UNIT #1 AND UNIT #2 WERE TRAVELING EAST ON SEC 564. DRIVER OF UNIT #2, MADE AN IMPROPER LANE CHANGE, STRIKING THE RIGHT SIDE OF THE UTILITY TRAILER BEING PULLED BY UNIT #1 WITH THE DRIVER'S SIDE MIRROR.

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other


Λ

17

5.15

Longitude

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



22255268 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1639 1716 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Collision 2- Alternate 7- Business N E 2 - US Primary 5 - County 07-07-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 N (E) Miles EGREES MINUTES SECONDS 0.03 CHROME DR s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other 0 П Latitude 34 50 3.06 1 - Interstate 4 Secondary 2 Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 548 / ROPER MOUNTAIN RD

S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit


Longitude

5 - Spur 9 - Other

17

26.06





/ HARTNESS DR


2 - US Primary 5 County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

NF



Unit 1 and unit 2 were both traveling east on Sec. 564. Unit 1 was attempting to pull to the shoulder of Sec. 564. The driver of unit 2 was driving too fast for conditions, causing unit 2 to strike unit 1.

2 - Alternate 7 - Business


5 - Spur 9 - Other

Longitude

15


49.60

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.



22263909 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1252 1555 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2 - US Primary 5 - County 2- Alternate 7- Business N E 08-09-2022 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 3 NF Miles EGREES MINUTES SECONDS 0.06 ROPER MOUNTAIN RD s (M) s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П Latitude 34 50 8.89 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id Ramp Only To g Second Intersection (Rt. # / Name) 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / CHROME DR Longitude 16 52.28 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other






UNIT #1 AND UNIT #2 WERE TRAVELING WEST ON SEC 564. THE DRIVER OF UNIT #2, DRIVING RECKLESSLY, ATTEMPTED TO CHANGE LANES, AND STRUCK UNIT #1. WITNESSES CONFIRMED THE DRIVER OF UNIT #2 WAS DRIVING HIGHLY ERRATIC AND AGGRESSIVE.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.


S W 2 - Exit



5 - Spur 9 - Other

S W 2-Exit






22268365 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 2120 2130 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 08-24-2022 23 564 / GARLINGTON RD GREENVILLE 0.2 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 10 1194, CHROME DR s w SW 5 - Spur 3 - SC Primary 6 - Other 7 - Ramp 9 - Other П Feet Latitude 34 49 56.78 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N F 1 - Entrance NF 1194 / CHROME DR Longitude 17 31.27

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2-Exit



5 - Spur 9 - Other



Unit #1 was traveling east on S-564. Unit #2 was stopped at a stop sign headed north on S-1194. Unit #2 then failed to yield the right of way and attempted to make a left turn. Unit #1 then struck Unit #2 on the driver's side of the vehicle.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name B.L.COMEAU


Rank LCPL

SCCJA# 6813-6628

Jurisdiction Code Review Date HP03 09-12-2022 HP03

Reviewer's Name C.J. LADUE

Internal Agency Code GVTC22CAD102629 Rank CPL



22277592 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1259 1306 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business (N) E 2 - US Primary 5 - County 09-21-2022 23 564 / GARLINGTON RD GREENVILLE S W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 3 Miles EGREES MINUTES SECONDS 0.05 492 , PELHAM RD s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other 0 П Latitude 34 51 25.73

g Second Intersection (Rt. # / Name)

999 / HONBARRIER DR

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

15

22.34

Longitude

1 - Interstate 4 Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

To


NF


Ramp Only

N F 1 - Entrance

S W 2 - Exit


R. R. Id





22278684 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1212 1242 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NE 2 - US Primary 5 - County 10-07-2022 23 GREENVILLE 564 / GARLINGTON RD S W 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Main line 6 - Connectio Direction 1 - Interstate GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 EGREES MINUTES SECONDS 5 **SNIPES RD** s (M) s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 36.26 1 - Interstate 4 - Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 County NF

HOKE SMITH BLVD



N F 1 - Entrance

S W 2 - Exit

S W 3 - SC Primary 6 - Other 7 - Ramp

Unit 1 was initially stopped at a stop sign on Snipes Road before attempting to cross Garlington Road onto Shamrock Lane. Unit 2, initially stopped at a stop sign on Shamrock Lane, failed to yield right of way to unit 1 before striking the left side of unit 1 with the left front. The driver of unit 2 was cited for failing to yield right of way.

Longitude

5 - Spur 9 - Other

16

13.72

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name M.A. FRANKS


Rank SGT

SCCJA# 8624-4557

Jurisdiction Code Review Date HP03 10-08-2022 HP03

Reviewer's Name M.A. FRANKS

Internal Agency Code GVTC22CAD125699 Rank SGT




22285151 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1350 1421 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 10-21-2022 1340 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 6 - PP 7 - Ramp 3 - SC Primary Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 6 Miles NF EGREES MINUTES SECONDS 0.2 146, WOODRUFF RD s w 3 SC Primary 6 - Other 7 - Ramp s (W) 5 - Spur 9 - Other Latitude 34 49 30.79 1 Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 385 / Longitude 17 43.87

5 - Spur 9 - Other


S W 3 - SC Primary 6 - Other 7 - Ramp


S W 2 - Exit



UNIT 1 WAS STOPPED FOR TRAFFIC SOUTHBOUND ON PRIVATE PROPERTY. UNIT 2 WAS TRAVELING WESTBOUND ON PRIVATE PROPERTY. UNIT 1, FAILING TO YIELD THE RIGHT OF WAY, ATTEMPTED A LEFT TURN ONTO SECONDARY 564 AND STRUCK THE RIGHT SIDE OF UNIT 2 WITH THE RIGHT FRONT OF UNIT 1. DRIVER OF UNIT 2 WAS OPERATING WITH A TRINIDAD DRIVERS LICENSE.


Rank CPL





S W 2 - Exit


Units 1 and 2 were traveling east on Garlington Road. Unit 1 slowed for other traffic that was turning into a private drive. Unit 2, following too closely, struck the center rear of unit 1 with the center front. The driver of unit 2 was cited for following too closely.



22290384 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 0223 0243 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Collision 2- Alternate 7- Business N E 2 - US Primary 5 - County 11-13-2022 23 564 / GARLINGTON RD 0.75 GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 NF Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.37 s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other 0 Latitude 34 50 8.48 1 - Interstate 4 Secondary Main line 6 - Connection R. R. Id Ramp Only To g Second Intersection (Rt. # / Name) 2 - US Primary 5 - County 2 - Alternate 7 - Business 0 N E N F 1 - Entrance 1112 / CHROME DR

S W 3 - SC Primary 6 - Other 7 - Ramp

S W 2-Exit




UNIT #1 WAS TRAVELING WEST ON SEC-564 WHEN A DEER ENTERED THE ROADWAY AND WAS STRUCK BY UNIT #1.

Longitude


5 - Spur 9 - Other

17

7.78



1142 / CHROME DR



N F 1 - Entrance

S W 2-Exit

N F

S W 3 - SC Primary 6 - Other 7 - Ramp


Unit 1 and unit 2 were traveling west on Sec. 564. Unit 1 and unit 2 stopped for traffic. Unit 2 made an improper start and struck unit 1 on the rear bumper.

Longitude

5 - Spur 9 - Other


17

43.81




22296014 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1654 1739 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business E E 2 - US Primary 5 - County 11-10-2022 1650 23 564 / GARLINGTON RD GREENVILLE 0.04 S W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset 4 - Secondary Base Intersec ion (Rt # / Name) NE 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 N (E) Miles DEGREES MINUTES SECONDS 0.01 DUBLIN RD s (M) 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Feet Latitude 34 50 15.54 1 - Interstate 4 Secondary g Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id To Ramp Only 2 - Alternate 7 - Business 0 N E 2 - US Primary 5 - County N F 1 - Entrance 548 / ROPER MOUNTAIN RD Longitude 16 44.14 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2-Exit 5 - Spur 9 - Other





HP03



999 / BOLAND CT

g Second Intersection (Rt. # / Name)

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

0

15

25.24

Longitude

1 - Interstate 4 Secondary

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

To


NF


Ramp Only


N F 1 - Entrance

S W 2 - Exit


R. R. Id







Unit 1 and unit 2 were traveling east on Sec. 564. Unit 1 and unit 2 stopped for traffic. Unit 2 made an improper start and struck unit 1 on the rear bumper.



g Second Intersection (Rt. # / Name)

/ CARRIE DR

1 - Interstate 4 - Secondary

S W 3 - SC Primary 6 - Other 7 - Ramp

2 - US Primary 5 County


To

NF

Ramp Only

N F 1 - Entrance

S W 2 - Exit



UNIT #1 WAS TRAVELING EAST ON SEC-564 WHEN A TREE FELL IN THE ROADWAY. UNIT #1 STRUCK THE TREE.

Latitude

Longitude

Main line 6 - Connection

2 - Alternate 7 - Business

5 - Spur 9 - Other

34

0

50

16


34.73

15.35

1/11/2023: CORRECTED REPORT TO SHOW BASE DISTANCE DIRECTION, TRAFFIC WAY, AND ROAD CHARACTER.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

R. R. Id



22303565 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1554 1622 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business NE 2 - US Primary 5 - County 12-05-2022 23 564 / GARLINGTON RD GREENVILLE (S) W 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 4 Miles EGREES MINUTES SECONDS 548, ROPER MOUNTAIN RD 0.11 s (W) s (M) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Latitude 34 50 8.20 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id Ramp Only To g Second Intersection (Rt. # / Name) 2 - Alternate 7 - Business 0 2 - US Primary 5 County N F 1 - Entrance NF / CHROME DR Longitude 16 54.69 S W 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other





Units 1 and 2 were traveling west on Secondary 564. Unit 1 was stopped at the stop light. Unit 2, driving too fast for conditions for wet road conditions, struck the right rear of unit 1 with the center front. The driver of unit 2 also stated her insurance had lapsed. The driver of unit 2 was cited for driving too fast for conditions and operating uninsured.

NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS THE FACTUAL ACCURACY THEREOF.

Investigating Officer's Name M.A. FRANKS

S W 2 - Exit


Rank SGT SCCJA# 8624-4557

Jurisdiction Code Review Date HP03 12-09-2022 HP03

Reviewer's Name M.A. FRANKS

Rank SGT

Internal Agency Code GVTC22CAD152779



548 / ROPER MOUNTAIN RD

2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

Investigating Officer's Name D. GONZALEZ

Rank TFC

SCCJA# 5482-9587

N F

2 - Alternate 7 - Business

9 - Other

5 - Spur

0

17


20.41

82

Internal Agency Code GVTC22CAD153292

Rank CPL


Longitude



Jurisdiction Code Review Date 12-18-2022

HP03

Reviewer's Name J. T. BUMGARNER



22305577 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY TRAFFIC COLLISION REPORT FORM of Original Report 2046 2147 TR-310 (Rev. 04/2016) 0-Main line 6- Connection Dir In Near City or Town of: Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 11-30-2022 2044 23 564 / GARLINGTON RD GREENVILLE SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) NE 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 Miles DEGREES MINUTES SECONDS 0.02 580 , DUBLIN RD s (M) 5 - Spur 3 - SC Primary 6 - Other 7 - Ramp SW 9 - Other П Latitude 34 50 15.99 1 - Interstate 4 Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R. R. Id Ramp Only To 2 - Alternate 7 - Business 0

548 / ROPER MOUNTAIN RD


2 - US Primary 5 - County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2 - Exit

NF




Unit #1 was stopped headed East on SEC#-564. The operator of Unit #1 was waiting to turn left onto Dublin Road. Unit #2 and Unit #3 were traveling East on SEC#-564 too fast for conditions. Unit #2 struck Unit #1 in the rear. Immediately after, Unit #3 struck Unit #2 in the rear. This collision pushed Unit #2 back into Unit #1.


Longitude

5 - Spur 9 - Other


16

43.55







HP03



22311791 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1857 1915 TR-310 (Rev. 04/2016) In Near City or Town of: 0-Main line 6- Connection Dir Date Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles 2- Alternate 7- Business N (E) 2 - US Primary 5 - County 12-30-2022 23 564 / GARLINGTON RD GREENVILLE 2.75 SW 5- Spur 3 - SC Primary 6 - PP 7 - Ramp Direction 1 - Interstate 4 - Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary (5) County 2 - Alternate 7 - Business Of 2 Miles EGREES MINUTES SECONDS 0.03 CHROME DR s w 3 - SC Primary 6 - Other 7 - Ramp SW 5 - Spur 9 - Other Latitude 34 49 55.43 1 Interstate 4 - Secondary Main line 6 - Connection R. R. Id To g Second Intersection (Rt. # / Name) Ramp Only 2 - Alternate 7 - Business 0 2 - US Primary 5 - County N F 1 - Entrance NF 385 / 1385 Longitude 17 31.49 S W 3 - SC Primary 6 - Other 7 - Ramp S W 2 - Exit 5 - Spur 9 - Other







22312009 **ORIGINAL** SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach Cop TRAFFIC COLLISION REPORT FORM of Original Report 1738 1842 TR-310 (Rev. 04/2016) 0-Main line 6- Connection In Near City or Town of: Time of 1 - Interstate 4 Secondary Collision Location (Rt. # / Name) Miles Dir 2- Alternate 7- Business N E 2 - US Primary 5 - County 12-30-2022 23 GREENVILLE 564 / GARLINGTON ROAD s w 6-PP 7-Ramp 5- Spur 3 - SC Primary Direction 1 - Interstate 4 Secondary Main line 6 - Connectio GPS COORDINATES 00 00'00.00" Distance Offset Base Intersec ion (Rt # / Name) N (E) 2 - US Primary 5 - County 2 - Alternate 7 - Business Of 2 NF Mile EGREES MINUTES SECONDS 10 1112 , CHROME DRIVE s w s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other П **Eee** Latitude 34 49 56.68 1 - Interstate 4 - Secondary Main line 6 - Connection R. R. Id To Second Intersection (Rt. # / Name) Ramp Only

/ GATEWAY ACCESS

2 - US Primary (5) County

S W 3 - SC Primary 6 - Other 7 - Ramp

N F 1 - Entrance

S W 2-Exit

N F




2 - Alternate 7 - Business

5 - Spur 9 - Other


Λ

31.27


Longitude





UNIT 2 WAS TRAVELING WESTBOUND ON SECONDARY 564. UNIT 1 WAS ATTEMPTING TO TURN LEFT FROM THE EASTBOUND LANE ON SECONDARY 564 ONTO SECONDARY 1112. UNIT 1 FAILED TO YIELD THE RIGHT OF WAY. THE FRONT OF UNIT 2 STRUCK THE REAR-RIGHT SIDE OF UNIT 1.





		UKI	GINAL														
	Partico Anti-S	CAROLINA DPS/OH	5 & DMV USE ON	ILY	Pag 1	e# Of: 1	CHARLESTON AND	SOUTH CAROLI COLLISION REP TR-310	THE STATE OF THE S	cure set acce	# Of Units 02	0	mended - Attach Copy f Original Report orrected	0.000	8 0 3	Arrived	d 16
02107	01-05-2022 Lane # / Dir.	Time of Count Collision 1 8 0 2 23	1- Interstate 2- US Primar 3- SC Primar	y 5-0	Secondary County PP 7-Ramp	And the second section is a	ocation (Rt. #		0-Main Line 2-Alternate 5-Spur	6-Connec 7-Busines	X10000.40880.505	es:	NE	In) Nea	ar City or T E	own of:	
20225	Lane # / Dir. # Of N	Distance O	Offset Direct	E 2-1	Interstate 4 US Primary 5	- County	ε	ntersection (Rt. #	SUASSE	\sim		6-Conn 7-Busi	ACCRECATION 1999		inates 00 (Rees Minu		B. 1578-50.
×	2 6 S R.R. Id.	W .13 From Rar			100000000000000000000000000000000000000	- Other 7- Ramp 1- Secondary		/ WOODRUF		5-Spu 0-Mai	-	9-Othe	er Latitu	de	34	49	33.96
		N E 1-E	ntrance N	I E 2- l	US Primary	County	war			2-Alte	ernate	7-Busin	ness	ıde	0	10	- 11
















ORIGINAL-CORRECTED




















































		O	CIGIIAN	1												
	SOUTH C	AROLINA DP	5/OHS & DMV (JSE ONLY	F 1	age #	TI	South Carol Raffic Collision Re TR-310		# Of Units 2016) 02	F	Amended - Attach Copy of Original Report Corrected	Notified	4 7	Arrived	5 5
8	Date 12-06-2022	Time of Collision	ounty 1- Inte 2- US F 23 3- SC P	rimary	Secondary 5- County 6- PP 7- Ram	72.27.20.00.00.00.00.00.00.00.00.00.00.00.00.		on (Rt. # / Name)	The second second second second	5-Connection A 7-Business	Ailes:	NE	In) Near	City or T	own of:	
N	Curic II / Dir.	140 97,000 4,000 0	nce Offset Miles	Direction N (E)	2- US Primary		Е	Base Intersection (Rt.	# / Name)	0-Main Line 2-Alternate		nnection GPS siness	COORDIN DEGRE	IATES 00 EES MINU		
202	1 5 S	.11 From	Ramp Only	1000		6- Other 7- Ramp Secondary	Fro	146 / WOODRU Second Intersection		5-Spur 0-Main Line	9-Ot	her Latitud	le	34	49	33.01
		ΝE	1- Entrance	ΝE	2- US Primary		ward		R	2-Alternate	7-Bu	siness Lonaitu	de	0	E	11




UNIT 2, WHILE TRAVELING SOUTHBOUND ON GARLINGTON ROAD IN THE LEFT TURN LANE, WAS STRUCK BY UNIT 1, WHICH WAS ATTEMPTING TO CROSS GARLINGTON RD FROM THE PARKING LOT OF 1137 WOODRUFF ROAD TO THE PARKING LOT OF 1143 WOODRUFF ROAD, CAUSING DAMAGE TO UNIT 2 AND UNIT 1.


NOTICE - THE TR-310 IS FOR STATISTICAL REPORTING PURPOSES ONLY AND IS A REFLECTION OF THE OFFICER'S BEST KNOWLEDGE, OPINION AND BELIEF COVERING THE COLLISION BUT NO WARRANT IS MADE AS TO THE FACTUAL ACCURACY THEREOF.

NO WANIMANT IS MINDERS TO THE TACTOR		TET THE TE					
Investigating Officer's Name	Rank	SCCIA#	Jurisdiction Code	Review Date	Reviewer's Name	Rank	Internal Agency Code
SALERNO - M J	PO 1	7057-8134	2 3 0 2	12-13-2022	TS Moore	PO3	22-081110




		UF	KIGINA	\L												
	SOUTH CAROLINA DPS/OHS & DMV USE ONLY					age # Of: 1	TRA	SOUTH CAROLI AFFIC COLLISION REF TR-310	THE WATER OF THE PARTY OF THE PARTY.	·/2016)	# Of Units 02	Amended - of Original Corrected		Notified 1748	Arrive	5 8
84520	12-05-2022	Collision	2- US P 3 3- SC P	rimary	Secondary 5- County 6- PP 7- Ran	The second second		(Rt. # / Name) NGTON RD	0-Main Line 2-Alternate 5-Spur	6-Connec 7-Busines	20000040888888	es: Dir. N E S W	_	Near City or	Town of	
S	curie ii / Biii	(I)	e Offset Miles	NE	1- Interstate 2- US Primary		Ε	Base Intersection (Rt.	# / Name)			i-Connection 7-Business	GPS (COORDINATES O DEGREES MIN		Berryana.
202	2 6 S R.R. ld.	W .10 From	Feet Ramp Only	To	1- Interstate	6- Other 7- Ramp Secondary		Second Intersection (I		5-Spu 0-Mai	-	9-Other 6-Connection	Latitude	34	49	31.37
		NE 1	- Entrance	ΝE	2- US Primary	5- County	war			2-Alte	ernate	7-Business	Lonaitud	de O		- 11





21250413 ORIGINAL SOUTH CAROLINA SOUTH CAROLINA DPS/OHS & DMV USE ONLY mended - Attach TRAFFIC COLLISION REPORT FORM lopy of Original Units 3 1808 1715 TR-310 (Rev. 04/2016) Main line 6- Connection Dir Time of County 1 - Interstate Secondary Collision Location (Rt. # / Name) Miles In Near City or Town of: 2- Alternate 7- Business 2 - US Primary 5 - County 06-16-2021 GREENVILLE 564 / GARLINGTON RD 1.1 0 S 3 - SC Primary 6 - PP 7 - Ramp 5- Sour Main line 6 - Connection GPS COORDINATES 00 00'00.00 Distance Offset 1 - Interstate 4 Secondary Base Intersection (Rt # / Name) N (E) 2 - Alternate 7 - Business NE 2 - US Primary 5 - County 01 DEGREES MINUTES SECONDS 0.03 548 , ROPER MOUNT AIN RD SW s (W) 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other Feet Lattude 34 50 11.43 1 - Interstate 4 - Secondary Second Intersection (Rt. # / Name) Main line 6 - Connection R.R.M To Ramp Only 2 - Alternate 7 - Business 0 N E 2 - US Primary (5) County N E 1 - Entrance DUBLIN RD .ongitude 82 48.26 16 3 - SC Primary 6 - Other 7 - Ramp 5 - Spur 9 - Other S W 2 - Exit S W





W. M. HIOTT

1529-5288

HP03

Page A Asian Danific Islander W. Com		2- Non-incar	nacitatina Le	Seating Lo	. l				1 -	Restraint/Sa	foty Dovice
	casian a) InjuryStatus r 0- Not Injured	3- Incapacit		eating Lo	20-1000		60- Sleeper				
3 - African American H - Hispanic O - Othe	1- Possible Inju		aung	/ \	30- Trailin		70- Riding or		101	one Used	21- Chik Safety S
- Alaskan Native or American IndianU - Unk				01 02 03 04 05 06			ow or Higher			houlder belt	
Air Bag Deployment / Switch Eject	5/2 0: 0 11::00	I Motorized Veh		07 08 09			Area (nontraili			ap Belt Only	88- Othe
1- Deployed Front 4- Not Deployed 1- Not Eje	rieda injui	y 1)Yes 2)		f			d Area (nontr	-		houlder & Lap i	
2- Deployed Side 7- Not Applicable 2- Part. E.	LOCATIONA	fter Impact	_	(non-mech)			d to Medical			strian, Motor/F	
3- Deployed Both 9- Deployment Unk. 3- Tot. Ex			4- Not Ap	-	1- Yes	2- No		Uknown			effective Cloth
1- Switch In On Position 3- No Switch 7- Not Ap 2- Switch In Off Position 9- Unknown 9- Unknown		Mechanical Mean		WII	b) By:	1-EMS	2- Police 8-	Other 9-1	Unk. 41-P	rotective Pads	61- Lighting
5º Olik.		nce of Events									
Ion-Collision 04- Equipment Failure		Collision: Not			Collision: F			bankment	55- Mail Box		68- Other
1- Cargo/Equip Loss or Shift 05- Fire/Explosion 08-		0- Animal (Deer Orl)			40- Bridge Over		e 48- Eq.	ipment	56- Mediani	Barrier	69- Unk.
		1- Animal (All Other)	40 10	E-min	41- Bridge Para		49- Fer		57- Overhead	d Sign Support	
		2- Motor Veh. (in Tr	22.04		42- Bridge Pier			ardrail End		ost, Pole, Support	
1 2 3 4		3- Mator Veh. (Stap)	Object		43- Bridge Rail		uardrail Face		59- Other (W	fall, Building, Tunr	nel, Etc.)
		4- Motor Veh. (Othe		- 1	44- Culvert		ighway Traffic S	-	60-		
23 23		5- Motor Veh. (Park	ed) 39-Un Object		45- Curb		npact Attenuato			Utility Pde	
25 25		6- Pedalcyde			46- Ditch	54- L	ight/Luminaire S	Support	62-	Work Zone Maint.	. Equipment
anner of Collision (Struck Veh.) 30- Rear-to			1st / Mo		1st Deform	med	1 7	7	Most Defo	med	1 7 7
00- Not Coll. w/ Motor Veh. 41- Angle (그		e Opposite Dir.	Deformed	Area	V 3	33	34 35	1 1	63 54 55	V6.	
	► ←) 70- Backed I		3 3	4 5/8	2	32 J		- 130 mg		7	74 SE_
20- Head Oil 43- Aligie ()			1 13	15 17 7	E 1 € 13 E	16 7	43	37	63	57 gn €	WIE-
71	,	ichool Bus	1	0 9 0	12 11	10 40	-	me[38 62]-m	ASPERT	- G	50
	Inimal Drawn Veh.62- P		7 1	1		41			61 60 59		
	Animal (Ridden) 98- O		21- Pedest	trian 81-N	lone 92-	Rollover	93- Total	94- Und	der Carriage	98- Other	99- Unk.
	Onto	Ink. (Hit and Rur			Drua Test			ng	Spe	ecial Use O	-
14- Other Truck 26- Other Motorbike 51- 1	raii		A2 D2		Cnown Results		lane	1	2 3	4 5	6 7
ehicle Use Code 04- Ambulance			A3 D3	2- Given - U			Refused		——,		Щ,
01- Personal 05- Military	09- Wrecker or Tow 1:		A1 D1	Test Type	_		1- Under- Ca			Underride/C	Override
01 02- Driver Training 06- Transport Passeng		8- Other	A2 D2	1- Breath (A							a Mana 2
					lic Only) 4-S		2- Under- No		4- Over MV in		6-Nane 2
01 03- Construction/Maint.07- Transport Property			A3 D3	2- Blood			2- Under- No 3- Under- Un		4- Over MV in 5- Over- Other		9- Unk. 3
Pehicle Attachment 4- Utility Trailer 8- To	wed Motor Vehicle C-	Other Tanker	DI.	2- Blood Results	8- C 3- Marijuana	Other	3- Under- Uni 0- Nane/Mina	known	5- Over- Other	Vehicle Extent of De	9- Unk. 3
dehicle Attachment 4- Utility Trailer 8- To 1 1- None 5- Farm Trailer 9- Pe	wed Motor Vehicle C- etroleum Tanker D-	Other Tanker Flat Bed	Drug Drug 1- Amp	2- Blood Results phetamines	8- C 3- Marijuana 4- Opiates	Other :	3- Under- Uni 0- None/Mino 2- Functional	known r Damage	5- Over- Other 4- Severe/Tota	Extent of De	9- Unk. 3
1 1- None 5- Farm Trailer 9- Pe 1 2- Mobile Home 6- Trailer w/ Boat A- Lo	owed Motor Vehicle C- etroleum Tanker D- owboy Trailer E-	Other Tanker Flat Bed Twin Trailers	Drug	2- Blood Results phetamines caine	8- C 3- Marijuana 4- Opiates 5- PCP	7- None :	3- Under- Uni 0- Nane/Mina	known r Damage Damage	5- Over- Other 4- Severe/Tota 5- Not Applical	Extent of De led 9- U	9- Unk. 3
1 1- None 5- Farm Trailer 9- Pe 1 2- Mobile Home 6- Trailer w/ Boat A- Lo	owed Motor Vehicle C- etroleum Tanker D- owboy Trailer E-	Other Tanker Flat Bed Twin Trailers Other	Drug D2 1- Amp D3 2- Coo	2- Blood Results phetamines caine esults 1- TV	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E	7- None : 8- Other	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D	known r Damage Damage 3- Two	5- Over- Other 4- Severe/Tota 5- Not Applical o-way, Divided,	Extent of De aled 9- U ble Barrier	9- Unk. 3 eformity 1 Ink. 2
1 1-None 5-Farm Trailer 8- To 1 2-Mobile Home 6-Trailer w/Boat A- Lo 1 3-Semi-Trailer 7-Camper Trailer b- Ac	owed Motor Vehicle C- etroleum Tanker D- owboy Trailer E-	Other Tanker Flat Bed Twin Trailers Other	Drug 1- Amp 2- Coc Alc Test Re	2- Blood Results phetamines caine esults 1- TV	8- C 3- Marijuana 4- Opiates 5- PCP	7- None : 8- Other	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D	known r Damage Damage	5- Over- Other 4- Severe/Tota 5- Not Applical o-way, Divided,	r Vehicle Extent of Dealed 9- Uble Barrier	9- Unk. 3
1	wed Motor Vehicle C- etroleum Tanker D- etroleum Tanker E- etrocarrier Trailer F-	Other Tanker Flat Bed Twin Trailers Other orist)	Drug 1 - Amp 2 - Coc Alc Test Re A1 - A2 -	2- Blood Results phetamines caine esults 1- Tv 2- Tv	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E	7- None : 8- Other Divided ded, Unprotedian 5- R	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling Dected Median oadway 7- Si	r Damage Damage 3- Two 4- One	5- Over- Other 4- Severe/Tota 5- Not Applical 6-way, Divided, 8-Way 8- 0 9- Unk. B: X-	r Vehicle Extent of De aled 9- U ble Barrier Other Tra	9- Unk. 3 eformity 1 Jnk. 2 3 afficwav
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location	Drug 1- Amp 2- Coc Alc Test Re	2- Blood Results phetamines caine esults 1- Ty A:	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid	7- None : 8- Other Divided died, Unprotedian 5- R	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling Dected Median oadway 7- Si	r Damage Damage 3- Two 4- One	5- Over- Other 4- Severe/Tota 5- Not Applical 6-way, Divided, 8-Way 8- 0 9- Unk. B: X-	r Vehicle Extent of De aled 9- U ble Barrier Other Tra walk: V 1st	9- Unk. 3 eformity 1 Ink. 3 afficwa v
Philips	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location	Drug 1 - Amp 2 - Coc Alc Test Re A1 - A2 -	2- Blood Results phetamines caine esults 1- Tv 2- Tv A: 2	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid	7- None : 8- Other Divided died, Unprotedian 5- Raddide 6- S	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling Dected Median oadway 7- Si	known r Damage Damage 3- Two 4- One dewalk utside Traffo.	5- Over- Other 4- Severe/Tota 5- Not Applical 6-way, Divided, 8-Way 8- 0 9- Unk. B: X-	Extent of Delaied 9- Uble Barrier Tra walk: N 9- U 1st Ev de	9- Unk. 3 eformity 1 Ink. 2 3 afficwav t Harmful 5 vent Loc.
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location	Drug 1- Amp 2- Coc Alc Test Re A1- A2- A3-	2- Blood Results phetamines caine esults 1- Tv 2- Tv A: 2	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Roo	7- None 8- Other Divided led, Unprotedian 5- R addide 6- S	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D ected Median oadway 7- Si houlder 8- O traight - Hillor urve - Level	known r Damage Samage 3- Two 4- One dewalk utside Traffo. 6- (4- Severe/Tota 5- Not Applicalway, Divided,Way 8- C 9- Unix. way B: X- 1- Y 2- Curve - On Gra Curve - Hillcres	Extent of De	9- Unk. 3 eformity 1 Ink. 2 3 afficwav t Harmful 5 vent Loc.
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location in Vehicle	Drug 1- Amp 2- Coc Alc Test Re A1- A2- A3-	2- Blood Results phetamines caine esults 1- Tr 2- Tr A: 2- St 1- Dr	8-C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Ma 2- Island 4- Ro traight - Level traight - On G ty 3- Snow	7- None 8- Other Divided led, Unprotedian 5- Radide 6- S rade 4- C	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D ected Median oadway 7- Si houlder 8- O traight - Hillor urve - Level	known r Damage kamage 3- Two 4- One dowalk utside Traffo,	4- Severe/Tota 5- Not Applicalway, Divided,Way 8- C 9- Unix. way B: X- 1- Y 2- Curve - On Gra Curve - Hillcres	Extent of De	9- Unk. 3 eformity 1 lnk. 2 3 afficwav t Harmful 5 ent Loc.
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- whoby Trailer E- stocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location in Vehicle	Drug 1- Amp 2- Coc Alc Test Re A1- A2- A3-	2- Blood Results phetamines caine esults 1- Tv 2- Tv A: 2 2- St	8-C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Ma 2- Island 4- Ro traight - Level traight - On G ty 3- Snow	7- None 8- Other Divided led, Unprotedian 5- Radside 6- S rade 4- C	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D ected Median oadway 7- Si houlder 8- O traight - Hillor urve - Level	Damage Damage 3- Two 4- One dewalk utside Traffo. 6- (Water (Star	4- Severe/Tota 5- Not Applicalway, Divided,Way 8- C 9- Unix. way B: X- 1- Y 2- Curve - On Gra Curve - Hillcres	Extent of De aled 9- U ble Barrier Tra walk: 1st Ev de t Road Ch	9- Unk. 3 eformity 1
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location in Vehicle	Drug 1- Amp 2- Coc Alc Test Re A1- A2- A3-	2- Blood Results phetamines caine esults 1- Tr 2- Tr A: 2- St 1- Dr 2- W	8 - C 3 - Marijuana 4 - Opiates 5 - PCP wo-way, Not E wo-way, Divid 1 - Gore 3 - Mo 2 - Island 4 - Roo traight - Level traight - On G ty 3 - Snow	7- None : 8- Other Divided led, Unprote dian 5- R adside 6- S rade 4- C / 5- loe 6- Cont	3- Under- Uni 0- Nane/Mino 2- Functional 3- Disabling D acted Median oadway 7- Si houlder 8- O traight - Hillor urve - Level	r Damage Damage 3-Two 4-One downlik utside Traffor eest 5-(6-(Water (Star	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Way B- C 9- Unix. Way B- C 1- Y 2- Curve - On Gra Curve - Hillcres nding, etc)	Extent of De sied 9- U ble Barrier Tra walk: N 9- U 1st Ev de t Road Ch	9- Unk. 3 eformity 1 2 3 3 4 4 4 4 4 4 4 4
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- whoby Trailer E- stocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cydling King	Drug 1- Amp 2- Coc Alc Test Re A1- A2- A3-	2- Blood Results phetamines caine esults 1- Tr 2- Tr A: 2- St 1- Dr 2- W 01- S	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Ma 2- Island 4- Roo traight - Level traight - On G ty 3- Snow et 4- Slush	7- None : 8- Other Divided ded, Unprotedian 5- R addide 6- S as S rade 4- C / 5- loe 1 6- Continget 2	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling E ected Median cadway 7- Si houlder 8- O traight - Hillor urve - Level aminate 8- G	r Damage Damage 3- Two 4- One dowalk utside Traffo 6- (Water (Star	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Way Divided, 1-Way 8- O 9- Unix. Way 1- Y 2- Curve - On Gra Curve - Hillcres nding, etc) 9- Unix.	Extent of De sied 9- U ble Barrier Tra walk: N 9- U 1st Ev de t Road Ch	9- Unk. 3 eformity 1
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- whoby Trailer E- stocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location in Vehicle Cycling cing moke , 8- Severe C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 4: 2- St 1- Dr 2- W 01- S 02- Flashing 11- RR (X-b	8 - C 3 - Marijuana 4 - Opiates 5 - PCP wo-way, Not E wo-way, Divid 1 - Gore 3 - Ma 2 - Island 4 - Rox traight - Level traight - On G ry 3 - Snow let 4 - Slush stop and Go L g Traffic Signa ucks, Light &	7- None 8- Other Divided led, Unproted led,	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling E ected Median coadway 7- Si houkier 8- Of traight - Hillor urve - Level 2- Officer or 12- Oncoming 11- Pavement	r Damage Samage 3- Two 4- One dewalk utside Traffor est 5- (6- (Water (Star Dither Flagman Emergenc Markings (5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - Hillcres 1- Y Vehicle (only) 43- Yiel	Extent of De ded 9- U ble Barrier Tra Walk: N 9- U 1st Ev de t Road Ch Road Ch Traffic C Tvi d Sign 51- F1	9- Urik. 3 eformity 1 2 3 3 3 4 4 4 4 4 4 4
Sehicle Attachment	wed Motor Vehicle C- etroleum Tanker D- whoby Trailer E- utocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Vorking or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow	Other Tanker Flat Bed Twin Trailers Other orist) ing Vehicle Location in Vehicle Cycling cing imoke , 8- Severe C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tv 2- Tv 1- Sv 2- Sv 01- S 02- Flashing 11- RR (X-b 12- RR (X-b	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Ro. traight - Level traight - On G raight - Level traight - On G traight - Siush Stop and Go L 1 Traffic Signa ucks, Light & ucks & Lights	7- None : 8- Other : Divided 8- Other : Divided 8- Other : Divided 8- Other : Standard	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median coadway 7- Si houlder 8- O traight - Hillor 7- V aminate 8- (21- Officer or 12- Oncoming 11- Pavement 11- Stop Sign	Damage Samage 3-Two 4-One dewalk utside Traffor est 5-(6-0) Water (Star Other Flagman Emergenc Markings (5- Over- Other 4- Severe/Tote 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillcres rding, etc) 9- Unk. 2y Vehicle (only) 43- Yiel 44- Wor	Extent of De ded 9- U ble Barrier Tra Walk: 1st Road Ch Road S Cond Traffic C Tvild Sign 51- Fire R Zone	9- Urik. 3 eformity 1 2 3 3 3 4 4 4 4 4 4 4
1	wed Motor Vehicle C- etroleum Tanker D- whoby Trailer E- utocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Vorking or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cycling cimoke , 8- Severe C 9- Unk. wet Lamp Not Lit)	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Ti 2- Ti 1- Si 1- Si 1- Si 1- RR (X-b 13- RR (X-b 13- RR (X-b	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Ro traight - Level traight - On G traight - Level traight - On G traight - Stop traight - Stop traight - Great traight - On G	7- None : 8- Other : Divided 8- Other : Divided 8- Other : Divided 8- Other : Divided 8- Other : Section	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median coadway 7- Si houlder 8- O traight - Hillor 7- V aminate 8- 0 21- Officer or 12- Oncoming 11- Pavement 11- Stop Sign 12- School Zo	r Damage Samage 3-Two 4-One dewalk utside Traffor est 5-(6-(Water (Star Other Flagman Emergenc Markings (5- Over- Other 4- Severe/Tote 5- Not Applical 5- Not Applical 5- Way B- C 9- Unk. 1- Y 2- Curve - On Gras Curve - Hillcres riding, etc) 9- Unk. 2y Vehicle (only) 43- Yiel 44- Wor 45- Oth	Extent of De ded 9- U ble Barrier Tra Walk: N 9- U 1st Ev de t Road Ch Road Ch Traffic C Tvi d Sign 51- F1	9- Unk. 3 eformity 1
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 7- Dark (No I	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cycling cimoke , 8- Severe C 9- Unk. wet Lamp Not Lit)	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- Sr 2- Sr 1- Dr 2- Sr 10- Sr 01- Sr 02- Flashing 11- RR (X-b 12- RR (X-b 13- RR (X-b 1- Yes, Direc	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Ro traight - Level traight - Level traight - Con G y 3- Snow let 4- Slush Stop and Go L y Traffic Signa ucks, Light & ucks & Lights ucks Only) city 2- Y	7- None 8- Other Divided led, Unprotedian 5- Radside 6- S and 4- C for Section 1 Secti	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median coadway 7-Si houlder 8-Or traight - Hillor unve - Level 7-1 aminate 8-(21- Officer or 12- Oncoming 11- Pawement 11- Stop Sign 12- School Zo by 3- No	conown r Damage Samage 3-Two 4-One dewalk utside Traffor eest 5-(6-(Water (Star Other Flagman Emergenc Markings (ne Sign 9-1	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - Hillcres 1- dding, etc) 9- Unk. 2- Vehicle (only) 43- Yiel 44- Wor 45- Oth	Extent of De died 9- U ble Barrier Tra Walk: 1st Road Ch Road S Cond Traffic (Tv) I d Sign 51- Fi fik Zone er Warning Sigchool Bus Ir	9- Unk. 3 eformity 1 2 3 3 3 4 4 4 4 4 4 4
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (No I	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cycling cimoke , 8- Severe Cy 9- Unk. set Lamp Not Lity Lights)	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- Sr 2- Sr 01- Sr 02- Flashing 11- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- bland 4- Ro traight - Level traight - Con G y 3- Snow let 4- Slush Stop and Go L y Traffic Signa urcks, Light & ucks & Lights ucks Only) city 2- Y st Sign 3	7- None 8- Other Divided led, Unprotedian 5- Radside 6- S and 4- C for Sight 2 (Gartes) 3- Sight 2 (Gartes) 4- C for Sight 2 (Gartes) 4- C for Sight 2 (Gartes) 3- Transition 3- Transition 3- Transition	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median coadway 7- Si houlder 8- O traight - Hillor unve - Level 7-1 aminate 8- O 21- Officer or 12- Oncoming 11- Pawment 11- Stop Sign 12- School Zo by 3- No	r Damage Samage 3- Two 4- One dewalk utside Traffo. rest 5- (6- (Water (Star Other Hagman J Emergence Markings (ne Sign 9- L Termination	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillcres rding, etc) 9- Unk. 2y Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 51 1- Yes 2- N	Extent of De ded 9- U ble Barrier Tra Walk: 1st Road Ch Road S Cond Traffic (Traffic	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Tehicle Attachment	wed Motor Vehicle C- troleum Tarker D- wboy Trailer E- tlocarrier Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 7- Dark (No I	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cycling cimoke , 8- Severe Cy 9- Unk. set Lamp Not Lity Lights)	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results Determines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- W 01- S 02- Flashing 11- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s 2- Advanced	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- bland 4- Ro traight - Level traight - Level traight - Con G y 3- Snow let 4- Slush Stop and Go L to Traffic Signa urcks, Light & ucks & Lights ucks Only) city 2- Y st Sign 3 d Warning Are	7- None 8- Other Divided led, Unprote dian 5- R addide 6- S and 4- C continuity of the dian 2- C continuity of the dian 3- S continuity of the dian 3- S continuity of the dian 3- S continuity of the dian 3- Transition and 4- Activities and 4- Act	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median coadway 7- Si houlder 8- O traight - Hillor unve - Level 7-1 aminate 8- O 21- Officer or 22- Oncoming 11- Pawement 11- Stop Sign 12- School Zo by 3- No n Area 5- O ty Area	r Damage Samage 3- Two 4- One downlik utside Traffo. rest 5- (6- (Water (Starr Other Markings (ne Sign 9- I Termination Area	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillcres rding, etc) 9- Unk. 2y Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 51 1- Yes 2- N	Extent of De ded 9- U ble Barrier Tra Walk: 1st Road Ch Road S Cond Traffic (Tv) d Sign 51- Fink Zone er Warning Sig Chool Bus Ir No Work Zone L	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Cros sing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, C 99- Unik. 27- Wook 6- Fog, Smog, S tail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre fled) 7- Dark (No I 07- Shared Use Paths 08- T-Intersection	Other Tanker Flat Bed Twin Trailers Other Orist) Ing Vehicle Location In Vehicle Cycling Cing Cing Cing Cing Cing Cing Cing C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- St 01- S 02- Flashing 11- RR (X-b 13- RR (X-b 1- Yes, Direc 1- Before 1s 2- Advances 1- Shoulder/	3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Roo traight - Level traight - On G y 3- Snow let 4- Slush Stop and Go L j Traffic Signa ucks & Lights ucks & Lights ucks Only) ctly 2- Y t Sign 3 d Warning Are Median Work	7- None : 8- Other Divided led, Unprote dian 5- R addide 6- S rade 4- C / 5- Ice Gates) 3 (6- Cantalled Light 2 (7- Cantalled Light	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor urve - Level 21- Officer or 12- Officer or 12- Overning 11- Stop Sign 12- School Zo 15- Young 15- Young 16- Young 17- Young 18- Young	Damage Damage 3- Two 4- One dowak utside Traffo. est 5- (6- (Water (Star Other Flagman Emergenc Markings (ne Sign 9- (Terminatior Area) Work	5- Over- Other 4- Severe/Tota 5- Not Applicat 5- Not Applicat 6- Way 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillores Iding, etc) 9- Unk. 2 y Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 1 - Yes 2- N	Extent of De sied 9- U bie Barrier Tra walk: 1st Road Ch Road S Cond Traffic (Tv. d Sign 51- Fix Zone Wow Work Zone L Work Zone L Work Zone L	9- Unk. 3 eformity 1
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Cros sing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, C 99- Unk. 27- Work 6- Fog, Smog, S tail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre fled) 7- Dark (No I 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle	Other Tanker Flat Bed Twin Trailers Other Orist) Ing Vehicle Location In Vehicle Cycling Cing Cing Cing Cing Cing Cing Cing C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results Determines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- W 01- S 02- Flashing 11- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s 2- Advanced	3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Roo traight - Level traight - On G y 3- Snow let 4- Slush Stop and Go L j Traffic Signa ucks & Lights ucks & Lights ucks Only) ctly 2- Y t Sign 3 d Warning Are Median Work	7- None : 8- Other Divided led, Unprote dian 5- R addide 6- S rade 4- C / 5- Ice Gates) 3 (6- Cantalled Light 2 (7- Cantalled Light	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor urve - Level 21- Officer or 12- Officer or 12- Overning 11- Stop Sign 12- School Zo 15- Young 15- Young 16- Young 17- Young 18- Young	Damage Damage 3- Two 4- One dowak utside Traffo. est 5- (6- (Water (Star Other Flagman Emergenc Markings (ne Sign 9- (Terminatior Area) Work	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Way 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillcresinding, etc) 9- Unk. 2y Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 51 1- Yes 2- N	Extent of De led 9- U ble Barrier Tra walk: 1st Ev de le Road Ch Road S Cond Traffic (Tvi d Sign 51- Fi fix Zone er Warning Sig Chool Bus Ir No Work Zone L Work Zone U Work	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, C 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirtor Snow 6- Dark (Stre 7- Dark (No I 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turr	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location in Vehicle Cycling cing cing cing cing cing cing cing c	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- St 01- S 02- Flashing 11- RR (X-b 13- RR (X-b 1- Yes, Direc 1- Before 1s 2- Advances 1- Shoulder/	8 - C 3 - Marijuana 4 - Opiates 5 - PCP wo-way, Not E wo-way, Divid 1 - Gore 3 - Me 2 - Island 4 - Roo traight - Level traight - On G ry 3 - Snow fet 4 - Slush Stop and Go L g Traffic Signa ucks & Lights ucks & Lights ucks & Lights ucks Only) ctly 2 - Y et Sign 3 d Warning Are Median Work	7- None : 8- Other Divided led, Unprote dian 5- R addide 6- S arade 4- C addide 6- S addid	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor urve - Level 7- 1 aminate 8- O 21- Officer or 12- Oncoming 11- Pavement 11- Stop Sign 12- School Zo by 3- No 1 Area 5- ity Area nittent/Moving Closure 8- O on-Motoris	conown T Damage Samage 3-Two 4-One downlik utside Traffor est 5-(6-(Water (Star Other Flagman Emergenc Markings (ne Sign 9-1 Terminatior Area g Work Other 9-U	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk 1- Y 2- Curve - Hillcres 1- Y 2- Curve - On Gra Curve - Hillcres 1- Y 2- Curve - On Gra Curve - Hillcres 1- Y 2- Curve - Hillcres 1- Y 2- Curve - On Gra Curve - Hillcres 1- Y 2- Curve - Hillcres 1- Y	Extent of De lee Barrier	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- whoy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Urik. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre filed) 7- Dark (No I 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Medical Related	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location In Vehicle Cycling cing cing cing cing cing cing cing c	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- W 01- S 02- Flashing 12- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s 2- Advanced 1- Shoulder/ 2- Lane Shift adway	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Ro traight - On G raight - Level traight - On G Traffic Signa ucks & Lights ucks & Lights ucks & Lights ucks & Lights ucks Only) ctly 2- Y st Sign 3 d Warning Are Median Work IVCrossover	7- None : 8- Other Divided led, Unprote dian 5- R addide 6- S addi	3- Under- Uni 0- Nane/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor urve - Level 2-1- Officer or 12- Oncoming 11- Stop Sign 12- School Zo by 3- No n Area 5- ity Area nittent/Moving Closure 8- O on-Motoris ive	conown T Damage Samage 3- Two 4- One dewalk utside Traffor est 5- (6-6) Water (Star Other Flagman Emergenc Markings (ne Sign 9- L Termination Area j Work Other 9- U	5- Over- Other 4- Severe/Tota 5- Not Applicat 5- Not Applicat 6- Way 8- C 9- Unk. 1- Y 2- Curve - Hillores 1- Unk. 2- Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 1- Yes 2- N Ink. 1- Yes 2- N Environme 60- Animal in	Extent of De la led 9- U ble Barrier Tra walk: N 9- U let Extent Of De la led 9- U let Extent Of De la let	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 107- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turr Medical Related Aggressive Operation of	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location n Vehicle Cycling cimoke , 8- Severe Cy 9- Unk. set Lamp Not Lit) Lights) s or Trail 12- Y - 13- Non 99- Unk	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Tr 2- Tr 1- St 2- St 1- Dr 2- W 01- S 02- Flashing 12- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s 2- Advanced 1- Shoulder/ 2- Lane Shift adway	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Ro. traight - Level traight - Level traight - On G in Gore traight - Level traight - On G in Gore traight - Level traight - On G in Gore traight - On G in G i	7- None 8- Other Divided ed, Unprotection 5- Sadde 4- Contaction 5- Sadde 4- Contaction 5- Sadde 4- Contaction 5- Transition a 4- Activity 3- Interrute 4- Lane Not 50- Instituting 5- Sadde 1-	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median oadway 7- Si houlder 8- Or traight - Hillor 2- Level 21- Officer or 12- Oncoming 11- Pavement 11- Stop Sign 12- School Zo by 3- No n Area nittent/Moving Closure 8- Or Mover Services Nor Illegallly in	Damage Damage 3-Two 4-One dawalk utside Trafflor est 5-(6-0) Water (Star Other Flagman Emergenc Markings (ne Sign 9-1 Fermination Area g Work Other 9-U t	5- Over- Other 4- Severe/Tota 5- Not Applicat 5- Not Applicat 6- Way 8- C 9- Unk. 1- Y 2- Curve - Hillores 1- Unk. 2- Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 1- Yes 2- N Ink. 1- Yes 2- N Environme 60- Animal in	Extent of De lee Barrier	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- whoy Trailer E- tocamer Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Urik. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre filed) 7- Dark (No I 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Medical Related	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location In Vehicle Cycling cing imoke , 8- Severe C 9- Unk Lights) sor Trail 12- Y - 13- Non 99- Unk In Of Vehicle 30-1 30-1 30-1 30-1 30-1 30-1 30-1 30-1	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines asine esults 1- Tv 2- Tv 1- Sv 1- Sv 1- Sv 1- RR (X-b 12- RR (X-b 13- RR (X-b 1- Pes fore 1s 2- Advanced 1- Shoulder/ 2- Lane Shift adway Work 4: Roadway	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Ma 2- Island 4- Roo Iraight - Level Iraight - Level Iraight - On G ny 3- Snow let 4- Slush Stop and Go L n Traffic Signa ucks, Light & ucks & Light & ucks & Light & ucks Only) city 2- Y str Sign 1 Warning Are Median Work IVCrossover 8- Other 9- Urrk	7- None 8- Other Divided led, Unprotedian 5- Radside 6- S a- S rade 4- C led	3- Under- Uni 0- Nane/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor urve - Level 2-1- Officer or 12- Oncoming 11- Stop Sign 12- School Zo by 3- No n Area 5- ity Area nittent/Moving Closure 8- O on-Motoris ive	conown T Damage Samage 3-Two 4-One downlik utside Traffo. est 5-(6-(Water (Star Other Flagman Emergence Markings (ne Sign 9-1 Terminatior Area J Work Other 9-U t Roadway W.	4- Severe/Tota 4- Severe/Tota 5- Not Applicalway, Divided,Way 8- C 9- Unk. 1- Y 2- Curve - Hillcres riding, etc) 9- Unk. 2: y Vehicle (anly) 43- Yiel 44- War 45- Oth Unk. 1- Yes 2- N Environme 60- Animal in 161- Glare	Extent of De la led 9- U ble Barrier Tra walk: N 9- U let Extent Of De la led 9- U let Extent Of De la let	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-moto 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 7- Dark (No I 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Made Aggressive Operation of Over-correcting/Over-s Swerving to Avoid Obje Wrong Side or Woog W	Other Tanker Flat Bed Twin Trailers Other Orist) Ing Vehicle Location In Vehicle Cyding Groke , 8- Severe C 9- Unk set Lamp Not Lit) Lights) Ing Vehicle Ing Ser Trail 12- Y - 13- Non 99- Unk Ing Ser Vehicle	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines asine esults 1- Tv 2- Tv 1- Sv 2- Sv 01- S 02- Flashing 11- RR (X-b 12- RR (X-b 13- RR (X-b 1- Yes, Direct 1- Before 1s 2- Advances 2- Advances 2- Lane Shift adwav Work 40 Roadway Condition (I.	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Mo 2- Island 4- Ro. traight - Level traight - On G ity 3- Snow let 4- Slush Stop and Go L ity Traffic Signa ucks, Light & ucks & Light & ucks & Light & ucks Conly) ctly 2- Y st Sign 3 d Warning Are Median Work tVCrossover 8- Other 9- Unk . e., Wet)	7- None 8- Other 1	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling E acted Median cadway 7- Si houlder 8- Or traight - Hillor aminate 8- (21- Officer or 12- Oncoming 11- Pavement 11- Stop Sign 12- School Zo by 3- No n Area nittent/Moving Closure 8- (3) on Motoris ive Jor Illegallly in to Yield R. of bible (Dark Signs, Sig and Signs, Si	mown T Damage Samage 3- Two 4- One dewalk utside Traffo. est 5- (6- (8- (8- (8- (8- (8- (8- (8- (8- (8- (8	4- Severe/Tota 4- Severe/Tota 5- Not Applicalway, Divided,Way 8- C 9- Unk. 1- Y 2- Curve - Hillcres riding, etc) 9- Unk. 2: y Vehicle (anly) 43- Yiel 44- War 45- Oth Unk. 1- Yes 2- N Environme 60- Animal in 161- Glare	Extent of De leed 9- U ble Barrier Tra leed 9- U ble Barrier Tra leed 19- U ble Barrier Sign 51- Fi k Zone er Warming Sign Chool Bus Ir leed 19- U ble Barrier Work Zone L Work Zone L Work Zone L Work Zone Barrier Ba	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
1	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S fail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 07- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Made Aggressive Operation of Over-correcting/Over-s Swerving to Avoid Obje Wrong Side or Wrong V Under the Influence	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location In Vehicle Cycling Simoke In Severe Constitution In Vehicle In Severe Constitution In Vehicle In I	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines saine esults 1- Tv 2- Tv 1- St 1- St 1- RR (X-b 12- RR (X-b 13- RR (X-b 1- Yes, Dire- 1- Shoulder/ 2- Lane Shift adway Work 44 Roadway Condition (Lumps	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- Island 4- Rox traight - Level traight - On G in Gore 1- Since traight - Level traight - On G in Gore traight - On G in G i	7- None 8- Other Divided ed, Unprotedian 5- Radaide 6- S and 4- C for S local and S local	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median oadway 7- Si houlder 8- O traight - Hillor unve - Level 2-1- Officer or 12- Oncoming 11- Pawement 11- Stop Sign 12- School Zo by 3- No n Area 5- ity Area nittent/Moving Closure 8- (on-Motoris ive Aor Illegallly in to Yield R. of ble (Dark Clo ger Crossing er Crossing	mown T Damage Samage 3- Two 4- One dewalk utside Traffo. est 5- (6- (8- (8- (8- (8- (8- (8- (8- (8- (8- (8	4- Severe/Tota 4- Severe/Tota 5- Not Applicatway, Divided,way B- C 9- Unk. 1- Y 2- Curve - Hillcres rding, etc) 9- Unk. 2 Vehicle (anly) 43- Yiel 44- War 45- Oth Unk. 1- Yes 2- N Environme 60- Animal in 161- Glare	Extent of Do led 9- U ble Barrier Tra Walk: 1st Ev de t Road Ch Road S Cond Traffic C Tv dd Sign 51- Fi k Zone er Warming Sig chool Bus Ir lo Work Zone Work Zone Work Zone 9 Workers i ental 62- Ob Road 63- We 68- Off Vehicle Defi	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
1	wed Motor Vehicle C- troleum Tarker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Cros sing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S tail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 17- Dark (No I 17- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Medical Related Aggressive Operation of Over-correcting/Over-s Swerving to Avoid Obje Wrong Side or Wrong V Under the Influence Vision Obscured (Within	Other Tanker Flat Bed Twin Trailers Other Orist) Ing Vehicle Location In Vehicle Cycling Cing Cing Cing Cing Cing Cing Cing C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines saine esults 1- Tv 2- Tv 1- St 1- St 1- RR (X-b 12- RR (X-b 13- RR (X-b 1- Yes, Dire- 1- Shoulder/ 2- Lane Shift adway Work 44 Roadway Condition (Lumps	8- C 3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Me 2- bland 4- Ro traight - Level traight - Level traight - Level traight - Con G traight - Level traight - Stop and Go L traffic Signa t	7- None 8- Other Divided led, Unproted and 5- Radio 6- S addid 6- S and 4- C and	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median oadway 7- Si houlder 8- O traight - Hillor unve - Level 7-1 aminate 8- (21- Officer or 12- Oncoming 11- Pawement 11- Stop Sign 12- School Zo by 3- No n Area 5- (by Area nittent/Moving Closure 8- (con-Motoris) we or Closure (Con-Motoris) we (Cond Signs, Sig ar Crossing	mown r Damage 3- Two 4- One downlik utside Traffo. rest 5- (6- (Water (Staro Diher Staro Markings (ne Sign 9- L Termination Area J Work Other 9- U t n Roadway W. shing) nals, Etc.	5- Over- Other 4- Severe/Tots 5- Not Applicat 5- Not Applicat 6- Way 8- C 9- Unix. 1- Y 2- Curve - Hillores 1- Hillores 1- Yes 2- N 1- Yes	Extent of De deed 9- U ble Barrier Tra (there of De	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 4 3 3
Sehicle Attachment	wed Motor Vehicle C- troleum Tanker D- wboy Trailer E- tocamer Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Crossing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, C 99- Unk.	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location In Vehicle Cycling Cycli	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines saine esults 1- Tv 2- Tv 1- St 1- St 1- RR (X-b 12- RR (X-b 13- RR (X-b 1- Yes, Dire- 1- Shoulder/ 2- Lane Shift adwav Work 44 Roadway Condition (Lumps one, Low, So	8- Officers 9- Unix.	7- None : 8- Other Divided led, Unprote dian 5- Radio 6- S addide	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median cadway 7- Si houlder 8- O traight - Hillor unve - Level 7- 1 aminate 8- O 21- Officer or i 22- Oncoming i11- Pavement i11- Stop Sign i22- School Zo by 3- No n Area 5- i ity Area nittent/Moving Closure 8- O on-Motoris ive ior Illegallly ir to Yield R. of bible (Dark Clo ard Signs, Sig er Crossing	mown Tomage Samage 3- Two 4- One dewalk utside Traffor est 5- (6- (Water (Star Other Flagman I Emergence Markings (me Sign 9- U Termination Area I) Work Other 9- U t In Roadway W. Whing) nals, Etc.	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 5- Not Applical 6- Way 8- C 9- Unk. 1- Y 2- Curve - Hillcres dding, etc) 9- Unk. 27 Vehicle (only) 43- Yiel 44- Wor 45- Oth Urk. 1- Yes 2- N Environme 60- Animal in 61- Glare	Extent of De ded 9- U ble Barrier Tra Walk: 1st Ev de t Road Ch Traffic Cond Sign 51- Frik Zone er Warning Sigchool Bus In North Zone L Work Zone L Work Zone L Work Zone 162- Ob Road 63- We 68- Off 76- Wir 77- Re and 78- Tru	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 3 3
Vehicle Attachment	wed Motor Vehicle C- troleum Tarker D- wboy Trailer E- tlocarrier Trailer F- (Non-motor 21- Approaching Leavi 22- Entering/Cros sing I 23- Playing/Working or 24- Pushing Vehicle 25- Standing 26- Walking, Playing, 0 99- Unk. 27- Work 6- Fog, Smog, S tail 7- Blowing Sand Oil, Dirt or Snow 6- Dark (Stre 17- Dark (No I 17- Shared Use Paths 08- T-Intersection 09- Traffic Circle Made an Improper Turn Medical Related Aggressive Operation of Over-correcting/Over-s Swerving to Avoid Obje Wrong Side or Wrong V Under the Influence Vision Obscured (Within	Other Tanker Flat Bed Twin Trailers Other Orist) ing Vehicle Location In Vehicle Cycling Cing Cing Cing Cing Cing Cing Cing C	Drug Drug Drug Drug Drug Drug Drug Drug	2- Blood Results phetamines caine esults 1- Ti 2- Ti 1- Di 2- St 1- St 2- St 1- St 1- RR (X-b 12- RR (X-b 13- RR (X-b 13- RR (X-b 13- RR (X-b 1- Yes, Dire- 1- Before 1s 2- Advanced 1- Shoulder/ 2- Lane Shift adwav Work 4- Work 4- Roadway Condition (L. umps one, Low, So Il Device (Le.	8- C3- Marijuana 4- Opiates 5- PCP wo-way, Not E wo-way, Divid 1- Gore 3- Mo 2- Island 4- Rox traight - Levei traight - Lore in Traffic Signa ucks, Light & ucks & Light &	7- None 8- Other 1	3- Under- Uni 0- None/Mino 2- Functional 3- Disabling D acted Median oadway 7- Si houlder 8- O traight - Hillor unve - Level 7-1 aminate 8- (21- Officer or 12- Oncoming 11- Pawement 11- Stop Sign 12- School Zo by 3- No n Area 5- (by Area nittent/Moving Closure 8- (con-Motoris) we or Closure (Con-Motoris) we (Cond Signs, Sig ar Crossing	mown Tomage Samage 3- Two 4- One dewalk utside Traffor est 5- (6- (Water (Star Other Flagman I Emergence Markings (me Sign 9- U Termination Area I) Work Other 9- U t In Roadway W. Whing) nals, Etc.	5- Over- Other 4- Severe/Tots 5- Not Applical 5- Not Applical 5- Not Applical 6- Vay 8- C 9- Unk. 1- Y 2- Curve - On Gra Curve - Hillcres riding, etc) 9- Unk. 27 Vehicle (only) 43- Yiel 44- Wor 45- Oth Unk. 1- Yes 2- N Environme 60- Animal in 161- Glare 70- Brakes 71- Steering 72- Power Pla	Extent of De leed 9- U ble Barrier Tra (her Tra	9- Unk. 3 eformity 1 2 3 3 3 4 3 3 3 3 3 3